



Overview: Part of spill impact on 16" Nun River – Kolocreek pipeline right of way at Aguobiri. Picture was taken during Joint Investigation of 5th May 2012.



Close up: Hacksaw cut on 16" Nun River – Kolocreek pipeline at Aguobiri. Picture was taken during Joint Investigation of 5th May 2012.