



Close-up: Spill due to hack saw cut on Akaso Well 10S flowline at Mbiama. Picture was taken during Joint Investigation of 16th September, 2011.