



Overview: Part of spill impact on 28" Trans Forcados pipeline right of way at Batan.
Picture taken during Joint Investigation of 8th October, 2011.



Close-up: Spill due to inward dent on 28" Trans Forcados pipeline at Batan. Picture
taken during Joint Investigation of 8th October, 2011.