

<u>Close up:</u> Illegal fittings on 36" Rumuekpe-Nkpoku Trans Niger pipeline at Aluu. Picture was taken during Joint Investigation of 20th June 2013.

1