



Overview: Part of spill impact on 12" Imo River-Ogale Trunk line at Owaza. Picture was taken during Joint Investigation of 20th August 2012.



Close-up: Illegal Fitting on 12" Imo River-Ogale Trunk line at Owaza. Picture was taken during Joint Investigation of 21st August 2012.