



Overview: Part of spill impact on Nembe Creek1 Well19S wellhead right of way at Mile1. Picture was taken during Joint Investigation of 28th September 2012.



Close up: Deep cut on Nembe Creek1 Well19S wellhead at Mile1. Picture was taken during Joint Investigation of 28th September 2012.