



Overview: Part of spill impact on Etelebou Well11 at Akenfa-Epie. Picture was taken during Joint Investigation of 24<sup>th</sup> January 2012.



Close-up: Tampered valve on Etelebou Well11 at Akenfa-Epie. Picture was taken during Joint Investigation of 24<sup>th</sup> January 2012.