



Overview: Part of spill impact on 6" Obigbo north – Ogale pipeline right of way at KomKom. Picture was taken during Joint Investigation of 24th February 2012.



Close up: Spill point on 6" Obigbo north – Ogale pipeline at KomKom. Picture was taken during Joint Investigation of 24th February 2012.