


Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline at Akaramini. Picture was taken during Joint Investigation of 23rd October 2013.



Close up: Spill due to Illegal fitting on 14" Okordia - Rumuekpe Pipeline at Akaramini.
Picture was taken during Joint Investigation of 23rd October 2013.

1