



Overview: Part of spill impact on 28" Trans Forcados Pipeline at Ugbokodo.
Picture was taken during Joint Investigation of 7th Dec. 2012.



Close-up: Illegal fitting on 28" Trans Forcados Pipeline at Ugbokodo.
Picture was taken during Joint Investigation of 12th Dec. 2012.



Close-up: Illegal fitting of wooden cofferdam on 28" Trans Forcados Pipeline at Ugbokodo.
Picture was taken during Joint Investigation of 12th Dec. 2012.