



Overview: Part of spill impact on Cawthorne Channel Well29T flowline right of way at Mbiama. Picture taken during Joint Investigation of 18<sup>th</sup> July, 2011



Close-up: Spill point on Cawthorne Channel Well29T flowline at Mbiama. Picture taken during Joint Investigation of 18<sup>th</sup> July, 2011