



Overview: Part of spill impact on 4" Obele-Ibaa pipeline at Ibaa. Picture was taken during Joint Investigation of 2<sup>nd</sup> July 2012.



Close up: Spill due to Hacksaw cut on 4" Obele-Ibaa pipeline at Ibaa. Picture was taken during Joint Investigation of 2<sup>nd</sup> July 2012. (Picture was rotated for clarity)