



Overview: Part of spill impact at 28" Nkpoku – Bomu Pipeline route in Aleto-Nchia-Eleme.
Picture was taken during Joint Investigation of 26 February 2012.



Close-up: Drilled holes on 28" Nkpoku – Bomu Pipeline at Aleto-Nchia-Eleme.
Picture was taken during Joint Investigation of 16 March 2012.