



Overview: Part of spill impact on 12" Afiesere - Eriemu Delivery Line at Afiesere.
Picture was taken during Joint Investigation of 2nd Oct. 2012.



Close-up: Explosive tear on 12" Afiesere - Eriemu Delivery Line at Afiesere.
Picture was taken during Joint Investigation of 2nd Oct. 2012.