



Overview: Part of spill impact on 24" Nembe Creek pipeline right of way at Sego. Picture was taken during Joint Investigation of 10<sup>th</sup> June 2012.



Close up: Illegal fittings on 24" Nembe Creek pipeline at Sego. Picture was taken during Joint Investigation of 10<sup>th</sup> June 2012.



Close up: Illegal fitting on 24" Nembe Creek pipeline at Sego. Picture was taken during Joint Investigation of 10<sup>th</sup> June 2012.