



Overview: Part of spill impact on 14" Okordia-Rumuekpe pipeline right of way at Ikarama. Picture was taken during Joint Investigation of 23<sup>rd</sup> October, 2011.



Close-up: Spill due to hacksaw cut on 14" Okordia-Rumuekpe pipeline at Ikarama. Picture was taken during Joint Investigation of 23<sup>rd</sup> October, 2011.