



Overview: Part of spill impact on 16" Egbema-Assa Pipeline At Umudike.
Picture was taken during Joint Investigation of 29th Sept. 2012.



Close-up: Explosive tear on 16" Egbema-Assa Pipeline At Umudike.
Picture was taken during Joint Investigation of 29th Sept. 2012.