

<u>Close up</u>: Hacksaw cut on Ubie Well4S flowline at Iduekpeye. Picture was taken during Joint Investigation of 13th March 2013.

1