



Closeup: Drilled hole on 24" Alakiri-Bonny pipeline at Fusokiri/Ilomaturu. Picture was taken during Joint Investigation of 2nd August 2012.



Close up: Non leaking drilled holes on 24" Alakiri-Bonny pipeline at Fusokiri/Ilomaturu. Picture was taken during Joint Investigation of 2nd August 2012.



Close up: Illegal fitting on 24" Alakiri-Bonny pipeline at Fusokiri/Ilomaturu. Picture was taken during Joint Investigation of 7th August 2012.