



Overview: Part of spill impact on 4" Ughelli Well2L flowline at Ekakpamre. Picture taken during Joint Investigation of 17th June, 2011



Close-up: Spill due to rupture on 4" Ughelli Well2L flowline at Ekakpamre. Picture taken during Joint Investigation of 17th June, 2011