



Overview: Part of spill impact on 18" Assa-Rumuekpe pipeline right of way at Egbeda.  
Picture was taken during Joint Investigation of 30<sup>th</sup> May 2012.



Close up: Hacksaw cut on 18" Assa-Rumuekpe pipeline at Egbeda. Picture was taken  
during Joint Investigation of 30<sup>th</sup> May 2012.