



Overview: Extent of the spill incident impact at Cawthorne 21 L Flowline route in Okumabio.  
Picture was taken during JIV of 24 January 2011



Close-up: Cut on Cawthorne 21 L Flowline in Okumabio. Picture was taken during JIV of  
24 January 2011