

SYNTHETIC TEST DOCUMENT — LIFE SCIENCES QUALITY ASSURANCE TEST DATASET — STRICTLY FOR DEMONSTRATION & VALIDATION

High Shear Mixer Lid Silicone Gasket Degradation and Seal Breach

1. GENERAL INCIDENT INFORMATION

Date of Occurrence:	2026-09-20	Discovery Source:	Pre-Cleaning Swab Inspection by QC Technician
Manufacturing Site:	Granulation Suite 1, Hyderabad API Center	Department / Area:	Oral Solid Dosage Manufacturing
Related Product / Material:	Ciprofloxacin 250mg Granulate	Batch / Lot Number:	CIP-7712

2. EVENT SUMMARY & DEVIATION DESCRIPTION

During post-granulation inspection of High Shear Granulator HSM-05, the food-grade silicone lid gasket was found to have a 12 mm partial tear along the interior lip with missing particulate matter totaling approximately 0.15 grams.

3. IMMEDIATE ACTIONS & CONTAINMENT MEASURES

Granulate batch CIP-7712 (total weight 185.0 kg) was held in stainless steel drums with red QA quarantine tags. Optical sorting and metal/foreign particulate sieve analysis requested.

4. INITIAL LOGGING VERIFICATION

Logged By: Operations Shift Lead Date: 2026-09-20	QA Reviewer: Quality Assurance On-Duty Date: 2026-09-20	Workflow Stage: Awaiting AI Extraction & Human Review
--	--	---