

Value	Name	Summary	Conformance
0	NoTimeGranularity	This indicates that the node is not currently synchronized with a UTC Time source and its clock is based on the Last Known Good UTC Time only.	M
1	MinutesGranularity	This indicates the node was synchronized to an upstream source in the past, but sufficient clock drift has occurred such that the clock error is now > 5 seconds.	M
2	SecondsGranularity	This indicates the node is synchronized to an upstream source using a low resolution protocol. UTC Time is accurate to ± 5 seconds.	M
3	MillisecondsGranularity	This indicates the node is synchronized to an upstream source using high resolution time-synchronization protocol such as NTP, or has built-in GNSS with some amount of jitter applying its GNSS timestamp. UTC Time is accurate to ± 50 ms.	M
4	MicrosecondsGranularity	This indicates the node is synchronized to an upstream source using a highly precise time-synchronization protocol such as PTP, or has built-in GNSS. UTC time is accurate to ± 10 μ s.	M

11.17.6.2. TimeSourceEnum Type

This data type is derived from [enum8](#).