

Value	Name	Summary	Conformance
3	DelayedOnQuery	Indicate a Node waiting after a Busy response.	M
4	Downloading	Indicate a Node currently in the process of downloading a software update.	M
5	Applying	Indicate a Node currently in the process of verifying and applying a software update.	M
6	DelayedOnApply	Indicate a Node waiting caused by AwaitNextAction response.	M
7	RollingBack	Indicate a Node in the process of recovering to a previous version.	M
8	DelayedOnUserConsent	Indicate a Node is capable of user consent.	M

Unknown Value

This value SHALL indicate that the current state is not yet determined. Nodes SHOULD attempt a better state reporting.

Idle Value

This value SHALL indicate a Node not yet in the process of software update, for example because it is awaiting the moment when a query will be made.

Querying Value

This value SHALL indicate a Node in the process of querying an OTA Provider with [QueryImage command](#), including during the process of awaiting a response to that command.

DelayedOnQuery Value

This value SHALL indicate a Node waiting because it received a prior [QueryImageResponse](#) with a [Status](#) field indicating Busy.

Downloading Value

This value SHALL indicate a Node currently in the process of downloading a software update.

Applying Value

This value SHALL indicate a Node currently in the process of verifying and applying a software