

Inspection Change Report

Generated: 2026-03-16 15:54:57

Run Information

	Baseline (Previous)	Current Run
Run ID	run_20260310_194742	run_20260311_143012
Timestamp	2026-03-10T19:52:52	2026-03-11T14:35:28
Objects Detected	8	7

Search prompts: fire extinguisher, exit sign

Change Summary

7	UNCHANGED
0	MOVED
0	NEW
1	MISSING

Total objects tracked: 8

MISSING (1)

Object	Last Known Position	Score
fire extinguisher	(3.68, 3.18, 0.98)	94%

UNCHANGED (7)

Object	Previous Position	Current Position	Distance	Score
exit sign	(-2.01, 4.24, 1.27)	(-2.05, 4.20, 1.30)	0.06m	82%
exit sign	(-4.34, 2.99, 1.35)	(-4.29, 3.04, 1.32)	0.08m	80%
fire extinguisher	(-0.74, 2.95, 0.42)	(-0.71, 2.92, 0.45)	0.05m	88%
exit sign	(3.67, 3.12, 1.15)	(3.71, 3.09, 1.17)	0.05m	69%
exit sign	(-3.18, 6.67, 1.05)	(-3.22, 6.71, 1.02)	0.06m	63%
exit sign	(-4.65, 7.58, 1.76)	(-4.61, 7.62, 1.73)	0.06m	54%
exit sign	(-2.04, 1.89, 0.92)	(-2.08, 1.92, 0.89)	0.05m	80%

Recommendations

1. 1 "fire extinguisher" not found in current run. Verify presence or confirm removal.