

DIXON LABORATORY

RELIABILITY TEST REPORT
ID: RP-0010

1. TEST OVERVIEW

Test Protocol	Pressure Sensor Life Test
Test Type	Reliability Test
Test Category	Pressure Sensor Life Test
Product Type	FATL
Station(s)	P1-S6,P1-S7,P1-S8,P1-S9,P1-S10
Duration	1 Days
Schedule	11 May 2026 - 11 May 2026
Status	PENDING_REVIEW

2. JUDGEMENT CRITERIA

* No abnormalities are allowed.

3. EXECUTION SUMMARY (DAILY LOGS)

S.No	Date	Cycles	Remarks / Observations
1	11/05	300	No abnormalities observed.

FINAL VERDICT: PENDING_REVIEW