

TITAN CONSTRUCTION LLC

1200 Commerce Way, Suite 300, Riverside, CA 92507

Phone: (951) 555-8800 | Fax: (951) 555-8801

WORKPLACE INCIDENT REPORT

Form WIR-2026-0147

INCIDENT INFORMATION

Report Date: February 8, 2026
Incident Date: February 8, 2026
Incident Time: 10:15 AM
Report Prepared By: Dave Peterson, Site Foreman
Project Name: Riverside Medical Plaza - Phase 2
Project Address: 450 Industrial Blvd, Riverside, CA 92507
Specific Location: Building C, 2nd Floor, East Wing

INJURED EMPLOYEE INFORMATION

Employee Name: Maria Elena Santos
Employee ID: TC-2022-0147
Date of Birth: March 14, 1988
Job Title: Carpenter II
Department: Field Operations
Supervisor: Dave Peterson
Hire Date: January 15, 2022
Phone: (951) 555-0147
Address: 2847 Maple Grove Dr, Apt 12, Riverside, CA 92501

INCIDENT DESCRIPTION

On February 8, 2026, at approximately 10:15 AM, employee Maria Elena Santos was performing drywall installation work on scaffolding located on the second floor of Building C, East Wing.

Sequence of Events:

1. Employee was standing on scaffolding platform approximately 15 feet above ground level
2. Employee was reaching to secure a drywall panel to the upper portion of the wall
3. The scaffolding plank beneath the employee shifted unexpectedly
4. Employee lost balance and fell from the scaffolding
5. Employee landed on concrete floor approximately 15 feet below

6. Coworkers Carlos Ramirez and James O'Brien witnessed the fall and immediately called for help
7. Site Foreman Dave Peterson called 911 at 10:17 AM
8. Paramedics arrived at 10:28 AM and transported employee to Riverside General Hospital

INJURIES SUSTAINED

- Suspected fracture to right wrist/forearm
- Head injury (employee was conscious but disoriented)
- Back pain
- Multiple visible bruises and abrasions to left side of body

WITNESSES

Name	Position	Contact
Carlos Ramirez	Carpenter	(951) 555-0234
James O'Brien	Electrician	(951) 555-0345

EQUIPMENT/CONDITIONS INVOLVED

- Scaffolding Type: Frame scaffolding, 3-tier
- Scaffolding Condition: Guardrails on east side were not in place at time of incident
- Weather Conditions: Clear, 68°F
- Lighting: Adequate natural lighting

IMMEDIATE ACTIONS TAKEN

1. Area was secured and cleared of all workers
2. 911 was called for emergency medical response
3. Employee's emergency contact was notified
4. Scaffolding was tagged out of service
5. Incident area was preserved for investigation

Dave Peterson
Site Foreman

Date: February 8, 2026

Sandra Mitchell
HR Director

Date: February 9, 2026

*This report must be submitted to HR within 24 hours of incident.
A copy will be forwarded to the Workers' Compensation carrier.*