

Workshop Job Card



Name Shama
Address , ,
Phone

Make/Model Toyota - Corolla Date 4 July 2014
Year
Type VIN
Reg. number NSW125 Engine no.
Odometer

No.	Request	Job Description	Timing	Notes
	Replace left hand side head light. Paint bumper. Scratch on the right door. General service	Task2 Task3 Task4 Task 5 Task 6 Task 7 Task 8 Task 9 Task 10 Task 12 Task 13 Task 15 Task 18		This car is old. Could not find required paint colour for bumper. Door is fixed anyway.