

 TÜVRheinland® Precisely Right.		
	Harmonized Factory Audit Report	

Initial Assessment		Surveillance Assessment	X	Re-Assessment	
---------------------------	--	--------------------------------	---	----------------------	--

Report No.:	KSA-20-12-2024-7993075
Factory name:	Sutter Industries S.p.A.
The auditor inspected the above referenced factory with the following results:	

Audit Summary			
Section	P = Pass	F = Fail	N = Not applicable
Incoming Goods	☒	☐	☐
Production Control	☒	☐	☐
Measuring Equipment	☒	☐	☐
Handling and Storage	☒	☐	☐
Product Verification Testing (PVT) and Complaint Handling	☒	☐	☐
Quality Records	☒	☐	☐

The requirements in respect to an orderly production and the audit of licensed products are							
☒	fulfilled	☐	fulfilled with condition	☐	not fulfilled	☐	not fulfilled
	no deviations		minor deviations		major deviations		safety affected deviations
	positive confirmation		corrections will be checked during next audit		document check of the corrective actions necessary		Re-audit necessary

Explanation / Remarks	
-----------------------	--


The factory will be visited again in	☒ one year	☐ earlier, due to re-audit
The audit was carried out (between) :	10:00am – 12:00 pm	

The result of the factory audit has been explained to the representative of the factory and has been acknowledged with below signature.

Date:20.12.2024
Location: Località Leigozze, 1- 15060 Borghetto Borbera (AL)- ITALY



Michele Dalmonte
TÜV Rheinland Auditor



Manuela Scaglia
Quality Control Manager

 TÜVRheinland® Precisely Right.		
	Harmonized Factory Audit Report	

1.0 General Information				
1.1 Manufacturer's registered name and factory location				
Manufacturer's registered name:	Sutter Industries S.p.A.		Job Title	
Street and no.:	Località Leigozze, 1			
Postal code:	15060			
City:	Borghetto Borbera			
Province:	AL			
Country:	Italy			
1.2 Factory representative name and contact data				
Manufacturer's representative name:	Manuela Scaglia			
Position:	Quality Control Manager			
Telephone:	Country Code: +39	City Code: 0143	Phone: 631324	
Fax:	Country Code: +39	City Code: 334	Phone: 6494201	
E-Mail:	manuela.scaglia@sutter.it			
Additional audit team member(s):	1 st Name		Job Title	
	2 nd Name		Job Title	
1.3 Factory details				
Factory Area Size:	60000mq	Number of employees :	190	
Products manufactured:	Products for cleaning and hygiene in households and professional envir.			
Product name:	ONDA PMC; CUAT NEXT; ONDA NEXT; DRY-MOK;INI-MOK; MULTI ECOCAPS ECOLABEL; BATH ECOCAPS ECOLABEL;FLOOR ECOCAPS ECOLABEL; MOBILI FRESH; TERGI INOX; DESCALER DW; DIAMOND ECOLABEL; PLURAL PLUS; APPLE ECOLABEL; EDELWEISS; RUBY ECOLABEL; CLEANER 2000; EMERALD ECOLABEL; SF 120; CRIS UL; FLASH ECOLABEL; SF 210 KG 5x4; DECALC; POM WC ECOLABEL; SF 210 ml; STRIPP 83; WASH; OXIPUR POWDER			
Product brand/trademark:	Sutter; Emulsio			
Main Subcontractors:				
1.4 Supporting documents				
Copy of certificates, if available:	ISO 9001 Yes ☒ No ☐ N/A ☐	ISO 14001 Yes ☒ No ☐ N/A ☐	ISO 45001 Yes ☒ No ☐ N/A ☐	GMP Yes ☐ No ☒ N/A ☐
Organization chart:	Yes ☒ No ☐ N/A ☐			
Company quality manual:	Yes ☒ No ☐ N/A ☐			
Control of Non-conforming Product:	Yes ☒ No ☐ N/A ☐			
Sample procedures / instructions / inspection criteria being used on site:	Yes ☒ No ☐ N/A ☐			
1.5 Photo documentation				
Manufacturing Plant Outlook	Yes ☒ No ☐ N/A ☐			
Each Floor/Workshop/Process	Yes ☒ No ☐ N/A ☐			
Material and Final Product Warehouse	Yes ☒ No ☐ N/A ☐			
Audit Equipment and Location	Yes ☒ No ☐ N/A ☐			
Photographs of the actual product, its packaging and trademark / brand name	Yes ☒ No ☐ N/A ☐			

 TÜVRheinland® Precisely Right.		
	Harmonized Factory Audit Report	

2.0 Verification of purchased components and materials which have a safety implication on the certified product (Incoming Inspection)

2.0 Does the manufacturer verify materials and components upon receipt? 2.1 Are written inspections/testing instructions adequate to check items? (Please indicate the inspection items, sample size, AQL.)	Yes ☒ No ☐ N/A ☐ Remarks:
2.2 Is there a procedure covering the way to handle non-conforming components and materials? (E.g.: Components and materials clearly identified and/or segregated to prevent unauthorised use?)	Yes ☒ No ☐ N/A ☐
2.3 Are records of the incoming inspection maintained and satisfactory? (Conforming / Non-conforming items)	Yes ☒ No ☐ N/A ☐

3.0 Production Control, Monitoring and Routine Tests

3.1 Are the Quality Assurance and manufacturing personnel adequately briefed on their duties?	Yes ☒ No ☐ N/A ☐
3.2 Do they have readily available up-to-date documents, manufacturing, preventive maintenance and test instructions, photographs / drawings / samples on all those parts, which have an impact on the safety of the finished products?	Yes ☒ No ☐ N/A ☐
3.3 Is there a procedure to ensure that all products will be tested or inspected according to the manufacturer's requirements?	Yes ☒ No ☐ N/A ☐
3.4 Is the production process controlled and are products examined at appropriate stages, including final inspection?	Yes ☒ No ☐ N/A ☐
3.5 Is there a procedure covering the way to handle non-conforming products?	Yes ☒ No ☐ N/A ☐
Procedure of handling non-conforming products (one or more boxed may be ticked) ☒ Automated segregation process ☒ Manual segregation process ☒ Non-conforming products are destroyed ☐ Non-conforming products are repaired ☒ Others (please give details): Recycled ☐ Details given on AUDITOR'S Information page	
3.6 Are records of routine tests and preventive maintenance stored and satisfactory?	Yes ☒ No ☐ N/A ☐

4.0 Calibration of Safety Test and Measuring Equipment

4.1 Is calibration method documented and accuracy traceable to a national standard?	Yes ☒ No ☐ N/A ☐
Calibration done by (several boxes may be ticked): ☒ Laboratory accredited according to ISO/IEC 17025 ☒ Test equipment manufacturer/supplier ☒ National metrology institute ☐ Other (please provide details):	
4.2 Is the equipment provided with a label or similar indicating the next 'calibration due' date or another method ensuring the valid calibration status?	Yes ☒ No ☐ N/A ☐

 TÜVRheinland® Precisely Right.		
	Harmonized Factory Audit Report	

4.3 Are the records for calibration of test and measuring equipment stored and satisfactory?	Yes ☒ No ☐ N/A ☐
4.4 Is the proper function of the test equipment verified with a simulated failure (dummy) or by other equivalent means?	Yes ☒ No ☐ N/A ☐
4.5 Is there a procedure requiring appropriate actions to be taken by the operator if a functional check is found to be unsatisfactory, including retest of product concerned?	Yes ☒ No ☐ N/A ☐

5.0 Handling and Storage	
5.1 Are the components and materials to be used for production stored and handled in a proper way?	Yes ☒ No ☐ N/A ☐
5.2 Are the finished products stored and handled in a proper way, concerning the applicable product category? <i>(e.g. Are food items stored in a clean, and temperature controlled storage area?)</i>	Yes ☒ No ☐ N/A ☐

6.0 Product Verification Testing (PVT) and Complaint Handling	
6.1 Is PVT conducted in accordance with procedures?	Yes ☒ No ☐ N/A ☐
6.2 Is there a procedure requiring actions to be taken if PVT are found to be unsatisfactory?	Yes ☒ No ☐ N/A ☐
6.3 Is there a procedure regarding how to handle customer complaints?	Yes ☒ No ☐ N/A ☐

7.0 Corrective actions in response to auditor's evaluation	
If there were any unsatisfactory findings entered in the previous factory audit report, have these been corrected? NOTE: If the audit Report is not available, tick 'N/A' and give details.	Yes ☐ No ☐ N/A ☒
Remarks:	

8.0 Quality Management System

If the manufacturer operates a Quality Management System, which kind of?

- ☐ Quality Management System NOT certified
☒ Quality Management System certified by an accredited Body
☐ Quality Management System certified by a non-accredited Body
☒ Copy of the certificate provided as appendix to this report

If the QMS is certified or assessed by an accredited or non-accredited Body, provide details and a copy of the certificate.

Details of QMS standard: ISO 9001:2015

Name of certification body: SGS ITALIA S.p.A.

Certificate no.: IT98/0141

Certificate issued date/Certificate expiry date: 08.06.2021 / 14.05.2025

9.0 Auditor Recommendations

9.1 List your findings on the AUDITORS EVALUATION page(s) If possible indicate also the corrective actions the manufacturer intends to take.

9.2 Give your recommendations by ticking the appropriate box

1	No unsatisfactory findings.	Grant or continue licensing	☒
2	Minor unsatisfactory finding(s).	Manufacturer's corrective action(s) will be checked at next visit Grant or continue licensing	☐
3	Major unsatisfactory finding(s). Safety not directly affected.	Manufacturer shall confirm corrective action(s). Grant or continue licensing. Special or early routine audit recommended for checking corrective action(s).	☐
4	Critical unsatisfactory finding(s), Safety directly affected.	Licensing refused/suspended and repeated factory audit recommended after the manufacturer has confirmed implementation of corrective action(s).	☐

A copy of this report shall be provided to the undersigned contact person who should be aware of the contents and sign for its receipt.

☐ Printed copy provided ☒ Electronic copy provided

Content of this report including findings as documented on Auditor's Findings page (if any) have been explained by the Auditor to the factory representative / contact person.

The responsibility for ensuring that a product is manufactured in accordance with the standard to which it was originally approved rests with the Licence Holder.

Date: 20.12.24

Date: 20.12.24

Auditor's name (printed letters):
MICHELE DALMONTE

Factory representative (printed letters) :
MANUELA SCAGLIA

Signature: _____

[Handwritten signature]

Signature: _____

Mauro Sephon

 TÜVRheinland® Precisely Right.		
	Harmonized Factory Audit Report	

Annexure 1 – Saudi Arabia (in case of no ISO 14001-certificate available, see also clause 1.4)

10.0 Checkpoints by standard ISO 14001	
10.1 Is there a training process on environmental protection in place to ensure that all workers receive training? Are training records maintained?	Yes ☐ No ☐ N/A ☐
10.2 Any EMS audit report or internal audit report of ISO 14001?	Yes ☐ No ☐ N/A ☐
10.3 Has the organization defined and documented its environmental policy?	Yes ☐ No ☐ N/A ☐
10.4 Has a procedure been established, implemented and maintained to identify the environmental aspects of its current and relevant past activities?	Yes ☐ No ☐ N/A ☐
10.5 Are the following environmental aspects considered in sufficient detail? • Air emission • Wastewater effluent • Waste management • Soil pollution • Raw material and natural resource usage • Hazardous and toxic material • Impact on wellbeing (e.g. noise, smell, heat, landscape, protection) • Utility, energy and resource • Other environmental specific issues on site such a housekeeping, storage, areas, piping	Yes ☐ No ☐ N/A ☐
10.6 Special Remarks on this section:	Yes ☐ No ☐ N/A ☐

 TÜVRheinland® Precisely Right.		
	Harmonized Factory Audit Report	

Annexure 3 – Saudi Arabia Factory Audit – Corrective Action Form

Report No.:	KSA-20-12-2024-7993075		
Factory name:	Sutter Industries S.p.A.		
Factory location:	Località Leigozze, 1- 15060 Borghetto Borbera (AL)- ITALY		
Findings	Corrective Action	Evaluation	
//	//	//	
Result	☒ Cleared ☐ Not Cleared		
Findings	Corrective Action	Evaluation	
//	//	//	
Result	☒ Cleared ☐ Not Cleared		
Findings	Corrective Action	Evaluation	
//		//	
Result	☒ Cleared ☐ Not Cleared		
Findings	Corrective Action	Evaluation	
//	//	//	
Result	☒ Cleared ☐ Not Cleared		
Factory Representative		TÜV Rheinland Representative	
Name	Manuela Scaglia	Name	Michele Dalmonte
Designation	Quality Control Manager	Designation	Lead Auditor
Date	20.12.24	Date	20.12.24
Signature		Signature	