


Date: Version: 1	<div style="text-align: center;"> SAFETY FIRST! Injury Notification </div>	
Page 1 of 2	Confidential – proprietary information AB InBev	Owner: VP Technical

Notification of: Incidente - Sin Lesión
--

Victim	
Name	LUIS ARMANDO LA TORRE MELENDEZ
Title	PRODUCTION OPERATOR
Status	Empleado ABInBev

Time of incident	
Date	domingo, 14 de abril de 2024
Time	21:15
Shift	Día laboral

Location	
Zone	MA
Country	Perú
Plant / Facility	San Juan
Department	E&F - Steam & Heating

What happened? (description of incident)	
Description of incident (what happened?)	<p>Siendo las 9:13 pm el operador de Planta de Fuerza escucha un sonido fuerte fuera de sala de operadores, sale a investigar y encuentra en el piso restos de luminaria en sendero peatonal. No había personal en la línea de fuego.</p> <p>Acciones inmediatas</p> <ol style="list-style-type: none"> 1. Se procede a corte de energía en ese punto 2. Se segrega la zona 3. Se coordina el recojo de restos de vidrio 4. Se procede a iniciar la investigación
Did this Injury Occur While Commuting To/From Work?	No
Is SIF?	Si
Immediate corrective actions taken	

Injury (description of injury)	
Nature of injury	
Body parts affected	


Date: Version: 1	<div>SAFETY FIRST!</div> <div>Injury Notification</div>	
Page 2 of 2	Confidential – proprietary information AB InBev	Owner: VP Technical

Imagen 001: Caída de luminaria en paso peatonal

