

Thank you — your approval has been recorded. We will be in touch to schedule the work.

Your Electrical Action Plan

PREPARED FOR	Malia Kahananui
PROPERTY	59-720 Kamehameha Hwy, Haleiwa
INSPECTED	August 19, 2026

Thank you for having us out on August 19, 2026. We completed a visual inspection of the electrical service at 59-720 Kamehameha Hwy, Haleiwa. We found 1 item that we consider a safety concern and recommend correcting right away, along with the other items below.

● Immediate Hazards

1

These are conditions we consider a safety risk and recommend correcting as soon as possible.

1. Main Panel — Multiple conductors are landed under single neutral bar terminals where only one is permitted. Separating these terminations is recommended.

● Recommended Maintenance

1

1. Main Panel — Rust, corrosion, moisture, or insect intrusion was found inside the panel. Left untreated this degrades connections and leads to overheating.

Approval

Approved by Malia Kahananui on August 19, 2026.

inspected.

Paumalu Electric · (808) 638-9054