

FITNESS CERTIFICATE FOR SCHOOL BUILDING

1. Name of the officer : *Antu A.V.*
2. Name of the school : *Mount Thabore central School Peechanickad.*
3. Location with name of Education Dist/Sub Dist : *Aluva - Angamaly.*
4. Classification of buildings as specified in column 4 of the application for fitness certificate : *Class rooms - 1 nos - 6.30 x 6.00 m
lab & library - 2 nos - 8.50 x 6.30 m
Computes lab & store - 2 nos - 6.30 x 6.00 m
office room & staff room - 2nd - 6.30 x 6.00*
- 5 Period for which the certificate is issued : *2016-17*
- 6 Nature of defect : *Nil*
- 7 a) Foudation and basement : *RCC Footing & R.R. masonry.*
b) Super structure : *Framed structure + cement solid block*
c) Doors and Windows : *wood + concrete.*
d) Wood work wrought and put up : *R.C.C*
e) Roof : *Cement concrete.*
f) Flooring
- 8 Any major defects modified which will render the building unsafe in any manner : *No.*
- 9 Whether maintenance works have been done properly : *Yes*
- 10 whether structure is sound or not for conducting classes : *Sound under normal weather conditions.*

Certified that the school was inspected by me on *17/5/2016* and found to be fit to conduct class for the period *.(academic year)*

Place *Angamaly.*
Date: *23/5/16*



Antu A.V.
Assistant Engineer
Local Self Govt. Department
Angamaly Municipality, Pin-683572
Mob.9744246592