



Typical Cleanroom Bay



Typical Cleanroom Bay



Corridor A




Corridor B



Central Corridor







Air Filtration Management, Inc.

P.O. Box 269
Bethlehem, PA 18016
(610) 867-3869

HEPA FILTER BENCH TEST

TEST DATE 8-5-03 TECHNICIAN R. Strub

PASSED

NOTES _____



Efficiency: 99.99
Pressure Drop: 0.33
Date Tested: 10/29/2002
Operator: **camacho**
Machine: **MS3**



1-800-526-5148



AIRFLOW

TEST DIRECTION

CAMFIL FARR P/N:



5053832

DESCRIPTION



D5-10.56-46.00-N-30-00-1D-3297

SHOP ORDER NO. - SERIAL NO.



A23138-040

DATE CODE

0230231

MINIMUM
EFFICIENCY
99.99

MICRON
.3

TARGET
(W.G.) ΔP
0.33

VELOCITY
(FPM)
100

AIRFLOW
(CFM)
286

DUCTED CEILING MODULE