

## TASK GROUP INSTRUCTION

AIM REV 20.11.4.0 (OCTOBER 2020)

|                                                                                                                                                                            |                            |                     |                    |                    |                |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|---------------------|--------------------|--------------------|----------------|
| <b>TGI NO.:</b>                                                                                                                                                            | <b>COMPONENT NAME:</b>     | <b>TYPE:</b>        | <b>PHASE:</b>      | <b>REPEAT:</b>     | <b>CHANGE:</b> |
|                                                                                                                                                                            | <b>STRL MBR 3-338-10-L</b> | <b>AY</b>           | <b>A</b>           | <b>0</b>           | <b>1</b>       |
| <b>SHIP/HULL NO.:</b>                                                                                                                                                      | <b>SHIP/HULL NAME:</b>     | <b>SYSTEM:</b>      | <b>PROJ/WO NO:</b> | <b>CASREP CAT:</b> |                |
| <b>DDG-115</b>                                                                                                                                                             | <b>USS RAFAEL PERALTA</b>  |                     | <b>K61</b>         |                    |                |
| <b>CU PHASE TITLE:</b>                                                                                                                                                     |                            |                     |                    |                    |                |
| <b>F/O - REPAIR TRANSVERSE BULKHEAD PLATE FR 338 IN 3-338-10-L</b>                                                                                                         |                            |                     |                    |                    |                |
| <b>PREPARING ACTIVITY:</b>                                                                                                                                                 |                            |                     |                    |                    |                |
| <b>PREPARED BY:</b>                                                                                                                                                        | <b>CODE</b>                | <b>PHONE</b>        | <b>DATE</b>        |                    |                |
| <b>SHUUCHI OOTSUBO</b>                                                                                                                                                     | <b>231B.</b>               | <b>315-243-7152</b> | <b>18-NOV-2025</b> |                    |                |
| <b>APPROVED BY:</b>                                                                                                                                                        | <b>CODE</b>                | <b>PHONE</b>        | <b>DATE</b>        |                    |                |
| <b>RYOUTA TAKAGI</b>                                                                                                                                                       | <b>231B.</b>               | <b>315-243-4502</b> | <b>18-NOV-2025</b> |                    |                |
| <b>CONCURRED BY:</b>                                                                                                                                                       | <b>CODE</b>                | <b>PHONE</b>        | <b>DATE</b>        |                    |                |
| <b>CONCURRED BY:</b>                                                                                                                                                       | <b>CODE</b>                | <b>PHONE</b>        | <b>DATE</b>        |                    |                |
| <b>CONCURRED BY:</b>                                                                                                                                                       | <b>CODE</b>                | <b>PHONE</b>        | <b>DATE</b>        |                    |                |
| <b>CONCURRED BY:</b>                                                                                                                                                       | <b>CODE</b>                | <b>PHONE</b>        | <b>DATE</b>        |                    |                |
| <b>REASON FOR WORK/NEED FOR CHANGE:</b>                                                                                                                                    |                            |                     |                    |                    |                |
| Required to delete the requirements of NSIs 009-107 and 009-009 in Paragraph 5.1 per Memorandum Ser240/002                                                                 |                            |                     |                    |                    |                |
| <b>CHANGE INSTRUCTIONS:</b>                                                                                                                                                |                            |                     |                    |                    |                |
| CH1: Revise Paragraph 5.1 to delete the requirements of NSIs 009-107 and 009-009. (01/19/2026)                                                                             |                            |                     |                    |                    |                |
| <b>SPECIAL REQUIREMENTS:</b>                                                                                                                                               |                            |                     |                    |                    |                |
| <b>This Work Affects a Fire Zone Boundary. Fabrication and/or Staging of a Non-Flammable Closure is Required. CLEANLINESS FOR PIPING SYSTEM/EQUIPMENT LEVEL II and III</b> |                            |                     |                    |                    |                |

## WORK CERTIFICATION SIGNATURES

|                                                                                      |                                       |                   |                   |               |
|--------------------------------------------------------------------------------------|---------------------------------------|-------------------|-------------------|---------------|
| <b>COMPLETION OF WORK REVIEW:</b>                                                    | <b>BADGE NO.:</b>                     | <b>SHOP/CODE:</b> | <b>PHONE:</b>     | <b>DATE:</b>  |
|                                                                                      |                                       |                   |                   |               |
| <b>ACCEPTANCE OF COMPLETED WORK</b>                                                  |                                       |                   |                   |               |
| <b>PHYSICAL INSPECTION</b>                                                           | <b>PHYSICAL INSPECTION COMPLETED:</b> | <b>BADGE NO.:</b> | <b>SHOP/CODE:</b> | <b>PHONE:</b> |
| <b>REQUIRED:</b> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |                                       |                   |                   |               |
| <b>RECORDS REVIEW:</b>                                                               | <b>BADGE NO.:</b>                     | <b>SHOP/CODE:</b> | <b>PHONE:</b>     | <b>DATE:</b>  |
|                                                                                      |                                       |                   |                   |               |



| LIST OF EFFECTIVE PAGES |         |         |         |         |         |         |         |         |         |
|-------------------------|---------|---------|---------|---------|---------|---------|---------|---------|---------|
| SHT NO.                 | CHG NO. | SHT NO. | CHG NO. | SHT NO. | CHG NO. | SHT NO. | CHG NO. | SHT NO. | CHG NO. |
| 1-5                     |         |         |         |         |         |         |         |         |         |
| J 1-2                   |         |         |         |         |         |         |         |         |         |
| M-1                     |         |         |         |         |         |         |         |         |         |
|                         |         |         |         |         |         |         |         |         |         |

# 1. SCOPE/PURPOSE

1.1 Title: Transverse Bulkhead Plate Frame 338 in 3-338-10-L; repair

1.2 Location of Work:

1.2.1 Crew Wash Room, Water Coset, and Shower (3-338-10-L)

1.2.2 Crew Living Space No. 5 (3-310-2-L)

1.2.3 Fuel Service Tank (5-300-2-F)

1.2.4 Fuel Receiving Tank Group -6 (5-308-2-F)

1.2.5 Access Trunk (3-308-2-T)

1.2.6 Crew Living Space No. 4 (3-300-1-L)

1.2.7 Crew Living Space No. 6 (3-338-3-L)

1.2.8 Crew Living Space No. 7 (3-350-2-L)

1.2.9 Passage (3-338-6-L)

1.2.10 Generator Room (3-370-0-E)

1.2.11 Air Conditioning Machinery and Pump Room (5-300-01-E)

1.3 Identification:

1.3.1 Quantity (One EA), Fuel Service Tank

Tank No.: 5-300-2-F

Capacity: 20,277 Gallons

1.3.2 Quantity (One EA), Fuel Receiving Tank Group-6

Tank No.: 5-308-2-F

Capacity: 30,032 Gallons

1.3.3 Quantity (One Lot/3 Tanks), Fuel Tank Group-5

Total Capacity: 69,695 Gallons

Required amount of water to dewater: 48,000 Gallons

1.3.3.1 Fuel Receiving Tank Group-5

Tank No.: 5-308-1-F

2 TGI NO.:

SHIP:

|                     |          |   |     |
|---------------------|----------|---|-----|
| STRL MBR 3-338-10-L | AY       | A | 0   |
| DDG-115             | CHG/VER: |   | 1/2 |

Capacity: 30,038 Gallons

### 1.3.3.2 Fuel Tank Group-5

Tank No.: 5-354-0-F

Capacity: 38,127 Gallons

### 1.3.3.3 Fuel Expansion Seawater Overflow Tank Group-5

Tank No.: 4-370-3-F

Capacity: 1,530 Gallons

### 1.3.4 Quantity (One Lot/3 Tanks), Fuel Tank Group-6

Total Capacity: 63,450 Gallons

Required amount of water to dewater: 48,000 Gallons

#### 1.3.4.1 Fuel Receiving Tank Group-6

Tank No.: 5-308-2-F

Capacity: 30,032 Gallons

#### 1.3.4.2 Fuel Tank Group-6

Tank No.: 5-370-0-F

Capacity: 31,545 Gallons

#### 1.3.4.3 Fuel Expansion Seawater Overflow Tank Group-6

Tank No.: 4-370-4-F

Capacity: 1,873 Gallons

### 1.3.5 Quantity (One Lot), Bulkhead Plate, Transverse Watertight Bulkhead, Frame 338 in 3-338-10-L and 3-310-2-L

Material: HTS, MIL-S-22698 GR DH-36, 7.65 LBs Plate

Remarks: See 2.3 for details

### 1.4 Security Classification: None.

### 1.5 Initial Condition:

#### 1.5.1 Potential Asbestos Hazard.

### 1.6 Contractor work start date: 7/27/2026

### 1.7 Contractor work completion date: 9/4/2026

## 2. **REFERENCES:**

| REF. NO. | DOCUMENT /DRAWING NUMBER | DOCUMENT/DRAWING TITLE                                                    | REV | CHG NO. | COPY REQ'D (Y/N) | SOURCE DOC (Y/N) | PARA | SEC | PG   | CHP |
|----------|--------------------------|---------------------------------------------------------------------------|-----|---------|------------------|------------------|------|-----|------|-----|
| 1        | NSI FY-26                | NAVSEA Standard Items                                                     | -   | 1       | N                |                  |      |     |      |     |
| 2        | LI FY-26                 | Local Standard Items                                                      | -   | ORG     | N                |                  |      |     |      |     |
| 3        | PDD 100-ELM-260008       | REPAIR PLAN OF CORRODED TRANSV WTRTT BHD 338 IN CREW WC & SH (3-338-10-L) | -   |         | Y                |                  |      |     | AL L |     |

3 TGI NO.:

SHIP:

STRL MBR 3-338-10-L

AY

A

0

DDG-115

CHG/VER:

1/2

### 3. APPENDICES:

- 3.1 Appendix "J" TGI Job Summary Information Sheet 1/27/2026 C1209.2 K. YOSHIDA
- 3.2 Appendix "M" TGI Material List
- 3.3 Appendix "D" Deficiency Form

### 4. GENERAL REQUIREMENTS:

- 4.1 Not Applicable.

### 5. PROCEDURE:

- 5.1 Accomplish the requirements of 099-902YO of 2.2 for each tank listed in 1.3.1 and 1.3.2.
  - 5.1.1 Accomplish the requirements of 099-909YO of 2.2 for each tank listed in 1.3.3 and 1.3.4.
    - 5.1.1.1 Accomplish the requirements of 009-009 of 2.1.
  - 5.1.2 Ensure General Cleaning must be Level II for each tank listed in 1.3.1.
  - 5.1.3 Ensure General Cleaning must be Level III for each tank listed in 1.3.2.
- 5.2 Prior to cutting of each existing bulkhead plate listed in 1.3.5, contact Code 250 to clarify actual defect location in accordance with Note 7 of 2.3.
- 5.3 Remove existing, fabricate and install new each bulkhead plate listed in 1.3.5 in accordance with 2.3.
  - 5.3.1 Accomplish the requirements of 009-012 of 2.1, including Table 2, Column(s) A, Lines One through 7.
  - 5.3.2 Accomplish the requirements of 009-025 of 2.1 for a local air hose test of each new weld of bulkhead plate listed in 1.3.5. Allowable leakage: None.
- 5.4 Accomplish the requirements of 009-032 of 2.1 for each new and disturbed surface.
- 5.5 Notes:
  - 5.5.1 Planner: Code 231B S. Ootsubo, 243-7152  
 Planner: Code 231B A. Suzuki, 243-0968  
 Planner: Code 233 M. Takemura, 080-9350-1458
  - 5.5.2 Work Integration Manager (WIM): Code 333 T. Yaginuma, 080-5419-0598
  - 5.5.3 Work per this instruction involves cutting an access (or removal of a door) through a fire zone bulkhead, through the hull of the ship above the turn of the bilge, through ventilation components (ducting, plenums, etc.), or through any air-tight, fume-tight or watertight bulkheads normally used to control air flow in the event of a shipboard fire. A nonflammable closure is required in accordance with COMNAVSEASYS COM MSG R 261400Z JUL 12. The closure, if not continuously in use, shall be staged near the access, readily visible and accessible, so that any emergency responder can install the closure to affect proper air flow onboard the ship.
  - 5.5.4 JCN OD01-1024 are related to this TGI.
- 5.6 Government Furnished Material (GFM):
  - 5.6.1 SRF-JRMC will provide GFM listed in Appendix "M".

|                     |          |   |     |
|---------------------|----------|---|-----|
| STRL MBR 3-338-10-L | AY       | A | 0   |
| DDG-115             | CHG/VER: |   | 1/2 |

5.7 SRF-JRMC will provide the following service work: (TGI No. 38K6164401S02)

5.7.1 [C740] Crane and crane rigging service.

5.7.2 [X99E] Utility service, electrical.

5.7.3 [X99M] Utilities service, including low pressure air supply, water supply, and steam supply.

5.7.4 [C106.1] Safety inspection for SRF-JRMC employees.

5.7.5 [C106.2] Gas free inspection for SRF-JRMC employees.

5.7.6 [C133] QA inspection for (G) symbol(s).

5.7.7 [C250] On-site engineering support for clarification of actual defect location.

|   |          |                     |          |   |     |
|---|----------|---------------------|----------|---|-----|
| 5 | TGI NO.: | STRL MBR 3-338-10-L | AY       | A | 0   |
|   | SHIP:    | DDG-115             | CHG/VER: |   | 1/2 |

APPENDIX "M"  
TGI MATERIAL LIST

|         |            |                     |       |        |         |                   |                |
|---------|------------|---------------------|-------|--------|---------|-------------------|----------------|
| SYSTEM: | PLANT NO.: | COMPONENT NAME:     | TYPE: | PHASE: | REPEAT: | CU PH<br>VERSION: | CASREP<br>CAT: |
|         |            | STRL MBR 3-338-10-L | AY    | A      | 0       | 2                 |                |

|                                                             |
|-------------------------------------------------------------|
| CU PHASE TITLE:                                             |
| F/O - REPAIR TRANSVERSE BULKHEAD PLATE FR 338 IN 3-338-10-L |

| MATERIAL REFERENCES |                            |                        |     |
|---------------------|----------------------------|------------------------|-----|
| REF<br>NO.          | DOCUMENT/DRAWING<br>NUMBER | DOCUMENT/DRAWING TITLE | REV |

|            |         |
|------------|---------|
| JOB ORDER: | KEY OP: |
| 38K6164401 | A01     |

| MATERIAL LIST |           |            |             |                                                                                                              |                   |                         |     |    |            |            |                      |                      |
|---------------|-----------|------------|-------------|--------------------------------------------------------------------------------------------------------------|-------------------|-------------------------|-----|----|------------|------------|----------------------|----------------------|
| ITEM<br>NO.   | PC<br>NO. | REF<br>NO. | M<br>/<br>C | DESCRIPTION                                                                                                  | STOCK<br>NUMBER   | GENERIC<br>MATL<br>TYPE | LVL | QA | HAZ<br>MAT | DOC<br>NO. | QTY<br>REQD/<br>UNIT | QTY<br>USED/<br>UNIT |
| 001           |           |            | M           | PLATE,ME, ORDER FOR KTR<br>SIZE: 4' X 2' =1 EA<br>ORIG: C231B, S. OOTSUBO,<br>243-7152                       | 9B 9515 002375350 |                         | NA  | 4  | N          | 53185056   | 8/SF                 |                      |
| 002           |           |            | M           | ADHESIVE, ORDER FOR KTR<br>USE FOR SEAL JOINER<br>BULKHEAD WET SPACE<br>ORIG: C231B, S. OOTSUBO,<br>243-7152 | 9B 8040 001429823 |                         | NA  | 4  | Y          | 53285130   | 5/KT                 |                      |

NOTES:

|     |          |                     |          |     |   |
|-----|----------|---------------------|----------|-----|---|
| M-1 | TGI NO.: | STRL MBR 3-338-10-L | AY       | A   | 0 |
|     | SHIP:    | DDG-115             | CHG/VER: | 1/2 |   |

☐ NUCLEAR☐ NON-NUCLEAR

## APPENDIX "D"

### DEFICIENCY FORM

|                               |                                  |                           |                            |           |            |               |
|-------------------------------|----------------------------------|---------------------------|----------------------------|-----------|------------|---------------|
| 1. SHIP/HULL NO.:             | 2a. DL or DR No.<br>(Circle One) | 2b. REVISION:             | 3a. COMPONENT NAME:        | 3b. TYPE: | 3c. PHASE: | 3d. REPEAT:   |
| <b>DDG-115</b>                |                                  |                           | <b>STRL MBR 3-338-10-L</b> | <b>AY</b> | <b>A</b>   | <b>0</b>      |
| 4a. ICN:<br><b>38K6164401</b> |                                  | 4b. KEY OP:<br><b>A01</b> | 5. LOC SPACE/LVL:          | FRAME:    | P/S/C:     | 6. CAUSED BY: |

7. DESCRIPTION:

|                |       |        |            |       |            |
|----------------|-------|--------|------------|-------|------------|
| 8. ORIGINATOR: | NAME: | BADGE: | SHOP/CODE: | DATE: | PHONE NO.: |
|----------------|-------|--------|------------|-------|------------|

9. CORRECTIVE ACTION:

|                |       |        |            |       |            |
|----------------|-------|--------|------------|-------|------------|
| 10. EVALUATOR: | NAME: | BADGE: | SHOP/CODE: | DATE: | PHONE NO.: |
|----------------|-------|--------|------------|-------|------------|

#### FOR NON-NUCLEAR USE ONLY

|                                            |                                    |                                             |
|--------------------------------------------|------------------------------------|---------------------------------------------|
| 11. RFD/RFW REQ'D <input type="checkbox"/> | LAR REQ'D <input type="checkbox"/> | SRD/PLAN REV REQ'D <input type="checkbox"/> |
| ILS MOD REQ'D <input type="checkbox"/>     | DWG NO.: _____ S/A NO.: _____      |                                             |

|                                |       |        |            |       |            |
|--------------------------------|-------|--------|------------|-------|------------|
| 12. ISOLATION<br>SATISFACTORY: | SIGN: | BADGE: | SHOP/CODE: | DATE: | PHONE NO.: |
|--------------------------------|-------|--------|------------|-------|------------|

|                                                                                     |       |        |            |       |           |
|-------------------------------------------------------------------------------------|-------|--------|------------|-------|-----------|
| 13. SUBSAFE OQE RECORD?<br>YES <input type="checkbox"/> NO <input type="checkbox"/> | SIGN: | BADGE: | SHOP/CODE: | DATE: | PHONE NO. |
|-------------------------------------------------------------------------------------|-------|--------|------------|-------|-----------|

|                                    |       |        |            |       |           |
|------------------------------------|-------|--------|------------|-------|-----------|
| 14. CORRECTIVE ACTION<br>COMPLETE: | SIGN: | BADGE: | SHOP/CODE: | DATE: | PHONE NO. |
|------------------------------------|-------|--------|------------|-------|-----------|

|                                                                                    |                           |        |            |       |           |
|------------------------------------------------------------------------------------|---------------------------|--------|------------|-------|-----------|
| 15. INSPECTION REQ'D?<br>:YES <input type="checkbox"/> NO <input type="checkbox"/> | INSPECTION COMPLETE/SIGN: | BADGE: | SHOP/CODE: | DATE: | PHONE NO. |
|------------------------------------------------------------------------------------|---------------------------|--------|------------|-------|-----------|

|                                          |       |        |            |       |           |
|------------------------------------------|-------|--------|------------|-------|-----------|
| 16. RECORDS REVIEW<br>COMPLETE (DR ONLY) | SIGN: | BADGE: | SHOP/CODE: | DATE: | PHONE NO. |
|------------------------------------------|-------|--------|------------|-------|-----------|

DL's ISSUED  
(DR ONLY)

☐ NON-NUCLEAR

|                   |                                  |               |                     |           |            |             |
|-------------------|----------------------------------|---------------|---------------------|-----------|------------|-------------|
| 1. SHIP/HULL NO.: | 2a. DL or DR No.<br>(Circle One) | 2b. REVISION: | 3a. COMPONENT NAME: | 3b. TYPE: | 3c. PHASE: | 3d. REPEAT: |
| DDG-115           |                                  |               | STRL MBR 3-338-10-L | AY        | A          | 0           |

This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.