

Construction Progress Documentation

Commercial steel building and surrounding site work



SEPTEMBER 15, 2026 | BUILDING AND SITE

TWO VISITS. ONE VISUAL RECORD.

A dated view of the steel-framed building, staged materials, equipment and surrounding earthwork.

CAPTURE DATES

September 9 and 15, 2026

IN THIS REPORT

02 Building and site comparison
03 Steel framing and roof views

PREPARED BY

Chris Steingrube
Angel Eye View LLC

Building and site

Two dated perspectives of the same construction site

SEPTEMBER 9, 2026



Steel-framed building with a raised crane, equipment and materials visible across the surrounding site.

SEPTEMBER 15, 2026



Steel-framed building with a lowered crane boom, staged steel, vehicles and earthmoving equipment visible.

Views are grouped by subject and date; camera positions differ between visits.

Steel framing and roof

Closer views of the structure and adjacent work area

SEPTEMBER 9, 2026



Visible steel columns and roof framing, partial roof covering, a raised crane and access equipment.

SEPTEMBER 15, 2026



Visible steel columns and roof framing, roof covering, crews and equipment along the building frontage.

Photography records visible site conditions at the time of each visit.