Shenoy Auto Works

H.No. 07, Dugar Road, Mango 946474
GSTIN: 06GM6464P1Z3 | Ph: +913695944064

Invoice No.	INV/103/26	**Date**	2026-06-19
Customer	Gautam Saraf	**Vehicle**	Maruti Suzuki Swift VXi
Reg. No.	HR80EH3546	**Job Card**	JC/5291

#	Description	Amount (Rs.)
1	Grille - replacement	2,800
2	Taillight - replacement	4,080
3	Side Mirror - replacement	3,350
4	Painting and finishing	2,630
5	Labour charges	1,930
Subtotal		**14,790**
GST @ 18%		**2,662**
Total Payable		**17,452**

Payment due on delivery. Warranty on replaced parts as per manufacturer terms. This is a computer-generated invoice.