

Job Card - Customer Copy

Job Card No: JOB-2026-0005	Open Date/Time: 14/05/2026 20:52	Claim No: CLM-2026-0005	SR Type: Accident
Gate In: 14/05/2026 20:51	Advisor: Anil Shinde	Expected Delivery:	Current KM: 5


Customer Details		Vehicle Details	
Name	anil Shinde	Vehicle Reg No	GJ05RX4384
Mobile	9274066210	Model	Tiago
Address	mohadi	Variant / Colour	Tiago XTA CNG / OPAL_WHITE
GST		Chassis / Engine	MAT626026RKC25545 / 1.5CR08KWXW27050

Vehicle Condition & Inventory


Normal Inventory	
Inventory Item Name's	Yes/No/No's
Jack	Yes
Tool Kit	Yes
Mud Flap	3
Floor Mat	4
LH Mirror	Yes
RH Mirror	Yes
Center Mirror	Yes
Battery	No
Stereo	No
Front Wiper	Yes
Rear Wiper	Yes
Extra Accessories	Yes

Tyre Inventory				
Pos	Make	Size	Depth	Wheel Cap
Front Left	MRF	175/70/R15	0.60	N
Front Right	ceat	175/70/R15	0.55	N
Rear Left	MRF	175/70/R15	0.64	Y
Rear Right	ceat	175/70/R15	0.59	N
Stepney	MRF	175/70/R15	0.59	N

Vehicle Fuel Status



Vehicle Damage Marking



Customer Requests / Repair Advice					
Sr	Job Code	Repair Details	Std Hrs	Parts Estimate	Labour Estimate
No labour details added					
Parts Total		0.00	Labour Total		0.00
GST			Estimated Bill		
Repair Instructions					

I authorize the dealer to execute the jobs using necessary material at my cost.I understand that the vehicle is being stored, repaired and tested at my risk. Date & Time : Customer Sln	I certify that the work has been done to my satisfaction and I have taken the delivery of the vehicle. I have been offered old parts/salvage by dealership.	I have been offered old parts/salvage by dealership.
Customer Signature	Customer Signature	Date

Thank You!

Job Card - Workshop Copy

Job Card No: JOB-2026-0005	Open Date/Time: 14/05/2026 20:52	Claim No: CLM-2026-0005	SR Type: Accident
Vehicle Reg No: GJ05RX4384	Current KM: 5	Advisor: Anil Shinde	Expected Delivery:

Customer Details		Vehicle Details	
Name	anil Shinde	Model	Tiago
Mobile	9274066210	Variant / Colour	Tiago XTA CNG / OPAL_WHITE
Address	mohadi	Chassis No	MAT626026RKC25545
City		Engine No	1.5CR08KWXW27050

Repair Advice by Service Advisor

Sr	Complaint Code	Job Code	Repair Details / Instructions	Std Hrs	Parts Est.	Labour Est.
No repair advice added						

Spare Parts / Lubricants

Sr	Part No	Description	Qty	Rate	Amount
No parts added					

Job Allocation

Team Leader		Technician	
Bay No		Repair Status	Pending

Cost Summary

Parts Total	0.00	Labour Total	0.00
GST		Net Total	

Repair Instructions

--

Add-on Jobs: 1. 2.	Pending Jobs: 1. 2.
---------------------------------	----------------------------------

Customer Signature	Service Advisor Signature	Team Leader Signature	Quality Inspector Signature
--------------------	---------------------------	-----------------------	-----------------------------