

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

Tenants	Mrs Mary Lewis
Property Address	19 Van Kleef Circuit, Darwin 0800
Date Report Completed	05 Sep 2023 by Jeremy Emms

Water Meter Reading Start	
Lease Commencement Date	29 Aug 2023
Vacate Date	29 Aug 2024

	Condition of premises at START of tenancy						Condition of premises at END of tenancy				
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Front Gardens	Y	Y	Y	Garden neat and tidy. Lawn could do with weed spray and fertiliser.							
Driveway	N	Y	Y	Some oil stains which could be jet cleaned							
Paving	Y	Y	Y	Clear of weeds							
Garden	Y	Y	Y	Black mulch laid which looks good							
Grass	Y	Y	Y	Mowed and edged							
Verandah	Y	Y	Y	Gutter replaced last winter no further leaking reported							
Letterbox/Street Number	Y	Y	Y	Numbering, clear and letterbox all good							
Gutters/Downpipes	Y	Y	Y	Clear of leaves, no problems to report							
Watering System	Y	Y	Y	Retic needs to be serviced this summer							
Entry/Exterior	Y	N	Y	Render chipped on front pillar							
Door	Y	Y	Y	Frosting film installed on front door							
Screen Door/Security	Y	Y	Y	Secure and working							

Tenant's Signature

Mary Lewis

Property Address 19 Van Kleef Circuit, Darwin

PAGE 1 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

	Condition of premises at START of tenancy						Condition of premises at END of tenancy				
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Door											
Entry Lighting	Y	Y	Y	Single downlights at entrance, tested and working							
Bricks	Y	Y	Y	Issues with render on front pillar. Refer photo.							
Garage	Y	Y	Y	Roller door working and three remotes tested							
Outside	Y	Y	Y								
Floor	Y	Y	Y	Clean, no oil marks							
Walls	Y	Y	Y								
Ceiling	Y	Y	Y	No cobwebs							
Lighting	Y	Y	Y	Fluro light with cover							
Points	Y	Y	Y								
Other	Y	Y	Y								
Lounge	Y	Y	Y	Neat and tidy							
Door	Y	Y	Y	Double doors painted white							
Floor	Y	Y	Y	Carpet freshly cleaned							
Skirting	Y	Y	Y								
Walls	Y	Y	Y	Painted white							

Tenant's Signature

Maryanne

Property Address 19 Van Kleef Circuit, Darwin

PAGE 2 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

	Condition of premises at START of tenancy						Condition of premises at END of tenancy					
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees	
Blinds	Y	Y	Y	Wiped clean								
Ceiling	Y	Y	Y	Painted white with no marks								
Lighting	Y	Y	Y	4 down lights all working, dimmer working								
Points	Y	Y	Y									
Corded Blinds and Window Coverings	Y	Y	Y									
Windows/Window Safety Devices	Y	Y	Y									
Ceiling Fan/Air Conditioner	Y	Y	Y	Tested and working								
Other	Y	Y	Y									
Bathroom 1	Y	Y	Y	Clean and tiles wiped clean								
Door	Y	Y	Y	Towel hook behind door								
Floor	Y	Y	Y	Tiles clean								
Walls	Y	Y	Y	Painted white								
Ceiling	Y	Y	Y	freshly painted white								
Lighting	Y	Y	Y									
Points	Y	Y	Y									

Tenant's Signature

Maryanne

Property Address 19 Van Kleef Circuit, Darwin

PAGE 3 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

	Condition of premises at START of tenancy						Condition of premises at END of tenancy				
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Windows/Window Safety Devices	Y	Y	Y								
Sink/Taps	Y	Y	Y								
Toilet	Y	Y	Y								
Shower/Bath/Taps	Y	Y	Y								
Mirror/Cabinet/Vanity	Y	Y	Y								
Towel Rails	Y	Y	N	Rail loose, handle requires tightening							
Toilet Roll Holder	Y	Y	Y								
Heating/Exhaust Fan/Vent	Y	Y	Y	Tested and working							
Corded Blinds and Window Coverings	Y	Y	Y								
Other	Y	Y	Y								
Bathroom 2	Y	Y	Y	A lovely inspection, no problems to report							
Door	Y	Y	Y								
Floor	Y	Y	Y								
Walls	Y	Y	Y								
Ceiling	Y	Y	Y								

Tenant's Signature

Maryanne

Property Address 19 Van Kleef Circuit, Darwin

PAGE 4 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

	Condition of premises at START of tenancy						Condition of premises at END of tenancy				
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Lighting	Y	Y	Y								
Points	Y	Y	Y								
Windows/Window Safety Devices	Y	Y	Y								
Sink/Taps	Y	Y	Y								
Toilet	Y	Y	Y								
Shower/Bath/Taps	Y	Y	Y								
Mirror/Cabinet/Vanity	Y	Y	Y								
Towel Rails	Y	Y	Y								
Toilet Roll Holder	Y	Y	Y								
Heating/Exhaust Fan/Vent	Y	Y	Y								
Corded Blinds and Window Coverings	Y	Y	Y								
Other	Y	Y	Y								
Bedroom 1	Y	Y	Y	Neat and tidy							
Door	Y	Y	Y	painted white							
Floor	Y	Y	Y	carpet clean, no stains							

Tenant's Signature

Maryanne

Property Address 19 Van Kleef Circuit, Darwin

PAGE 5 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

	Condition of premises at START of tenancy						Condition of premises at END of tenancy				
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Lighting	Y	Y	Y	tested and working							
Windows/Window Safety Devices	N	Y	Y	Windows need cleaning							
Bedroom 2	Y	Y	Y								
Door	Y	Y	Y								
Floor	Y	Y	Y								
Skirting	Y	Y	Y								
Walls	Y	Y	Y								
Ceiling	Y	Y	Y								
Lighting	Y	Y	Y								
Points	Y	Y	Y								
Corded Blinds and Window Coverings	Y	Y	Y								
Wardrobe/Drawers/ Shelves	Y	Y	Y								
Windows/Window Safety Devices	Y	Y	Y								
Ceiling Fan/Air Conditioner	Y	Y	Y								
Other	Y	Y	Y								

Tenant's Signature

Maryanne

Property Address 19 Van Kleef Circuit, Darwin

PAGE 6 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

	Condition of premises at START of tenancy						Condition of premises at END of tenancy				
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Bedroom 3	Y	Y	Y								
Door	Y	Y	Y								
Floor	Y	Y	Y								
Skirting	Y	Y	Y								
Walls	Y	Y	Y								
Ceiling	Y	Y	Y								
Lighting	Y	Y	Y								
Points	Y	Y	Y								
Corded Blinds and Window Coverings	Y	Y	Y								
Wardrobe/Drawers/ Shelves	Y	Y	Y								
Windows/Window Safety Devices	Y	Y	Y								
Ceiling Fan/Air Conditioner	Y	Y	Y								
Other	Y	Y	Y								
Kitchen/Meals	Y	N	N	Pantry sensor light, not working and pantry door, scraping on floor							
Bench	Y	Y	Y	No noted marks							

Tenant's Signature

Maryanne

Property Address 19 Van Kleef Circuit, Darwin

PAGE 7 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

	Condition of premises at START of tenancy						Condition of premises at END of tenancy				
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Oven	Y	Y	Y	Well cleaned							
RHood	Y	Y	Y	Free from grease							
Pantry	Y	N	N	Pant light sensor is not working and the pantry door is scraping on the wooden floor. It requires adjusting							
Theatre Room	Y	Y	Y	Carpet clean, no stains							
Door	Y	Y	Y	Double doors painted white							
Floor	Y	Y	Y	Carpet has no stains							
Walls	Y	Y	Y	No marks							
Ceiling	Y	Y	Y	Painted white							
Lighting	Y	Y	Y	Dimmers installed							
Dining	Y	Y	Y	A lovely inspection, no problems to report							
Door	Y	Y	Y								
Floor	Y	Y	Y								
Skirting	Y	Y	Y								
Walls	Y	Y	Y								
Ceiling	Y	Y	Y								

Tenant's Signature

Maryanne

Property Address 19 Van Kleef Circuit, Darwin

PAGE 8 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

	Condition of premises at START of tenancy						Condition of premises at END of tenancy				
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Lighting	Y	Y	Y								
Points	Y	Y	Y								
Windows/Window Safety Devices	Y	Y	Y								
Corded Blinds and Window Coverings	Y	Y	Y								
Ceiling Fan/Air Conditioner	Y	Y	Y								
Other	Y	Y	Y								
Toilet	Y	Y	Y	No problems to report							
Door	Y	Y	Y								
Floor	Y	Y	Y								
Walls	Y	Y	Y								
Toilet	Y	Y	Y								
Roll Holder	Y	Y	Y								
Ceiling	Y	Y	Y								
Lighting	Y	Y	Y								
Windows/Window Safety Devices	Y	Y	Y								

Tenant's Signature

Maryanne

Property Address 19 Van Kleef Circuit, Darwin

PAGE 9 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

	Condition of premises at START of tenancy					Condition of premises at END of tenancy					
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Sink	Y	Y	Y								
Corded Blinds and Window Coverings	Y	Y	Y								
Other	Y	Y	Y								
Laundry	Y	N	Y	The paint is peeling along the walls, this indicates damp from dryer, as it is not ventilated.							
Walls	Y	Y	Y	Paint peeling and requires repainting							
Trough	Y	N	Y	Showing signs of rust							
Rear Gardens	Y	N	Y	Neat and tidy							
Paving	Y	Y	Y	Clear of weeds							
Grass	Y	Y	Y	Some holes where the dog has dug , but otherwise very neat the grass has been mowed and edged.							
Security/Safety	Y	Y	Y	Security doors or working House alarm tested and working							
Smoke Alarms	Y	Y	Y	tested and working							
RCD/Safety Switch	Y	Y	Y	Compliant with regulations							

Tenant's Signature

Maryanne

Property Address 19 Van Kleef Circuit, Darwin

PAGE 10 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

COMMENCEMENT	05 Sep 2023	TERMINATION	/ /
PROPERTY INSPECTOR	Jeremy Emms	PROPERTY INSPECTOR	
SIGNATURE		SIGNATURE	
DATE	05 Sep 2023	DATE	/ /
TENANT(S):	Mrs Mary Lewis	TENANT(S):	
SIGNATURE		SIGNATURE	
DATE	4 Sep 2023	DATE	/ /

Tenant's Signature



Property Address 19 Van Kleef Circuit, Darwin

PAGE 11 OF 12

NT – Entry Property Condition Report



PIM Inspections

PO Box 999, Darwin NT 0800

Phone: 1300 668 594

support@propertyinspectionmanager.com

View your photos/videos online via [Gallery Link](#)

Media

[Front Gardens:](#)

Photo Taken : 09/08/2023



[Front Gardens:](#)

Video Taken : 01/09/2023



[Entry/Exterior:](#)

Photo Taken : 09/08/2023



[Entry/Exterior:](#)

Photo Taken : 09/08/2023



[Garage:](#)

Photo Taken : 09/08/2023



[Bathroom 1:](#)

Photo Taken : 09/08/2023



[Bedroom 1:](#)

Photo Taken : 09/08/2023



[Kitchen/Meals:](#)

Photo Taken : 09/08/2023



[Laundry:](#)

Photo Taken : 09/08/2023



[Rear Gardens:](#)

Photo Taken : 09/08/2023



[Rear Gardens:](#)

Photo Taken : 09/08/2023



[Rear Gardens:](#)

Video Taken : 09/08/2023



Tenant's Signature

Maryolu

Property Address 19 Van Kleef Circuit, Darwin

PAGE 12 OF 12