

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

How to complete this report

1. Three copies of this condition report should be completed and signed by the landlord or the landlord's agent.

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

(b) At the end of the tenancy, the premises will be inspected and the condition compared to that stated in the original condition report.

(d) A condition report must be filled out whether or not a rental bond is paid.

Address of the premises

12/45 Wattle Grove

Riverstone, NSW

2765

Full name/s of the tenant/s

Marcus Ellery

Name of the lessor/agent

Owen Brackley - Meridian Property Group

The tenant/s received a copy of this report on (date):

Insert Y/3= Yes

Insert N/7= No

Tenant/s
Comments (if any)

Lessor/agent
Comment on tenant/s report

	C	n	a	e	i	d	e	g	a	m	a	d	n	U	g	n	i	k	r	g	W	new-ten	old-ten
Entrance/hall																							
front door/screen door /security door	N		Y		Y																		Dust buildup noted, otherwise serviceable
walls/picture hooks	N		N		Y																		Plaster scraped near the edge, hooks displaced
doorway frames	N		Y		Y																		Dust buildup noted, otherwise serviceable
windows/screens/ window safety devices																							
ceiling/light fittings	Y		Y		Y																		All in working order
blinds/curtains																							
lights/power points/ door bell	N		Y		Y																		Dust buildup noted, otherwise serviceable
skirting boards	N		Y		Y																		Dust buildup noted, otherwise serviceable
floor coverings	N		N		Y																		Visible wear across the main walkway
other																							
Lounge room																							
walls/picture hooks	N		N		Y																		Plaster scraped near the edge, hooks displaced
doors/doorway frames	N		Y		Y																		Dust buildup noted, otherwise serviceable
windows/screens/ window safety devices																							
ceiling/light fittings	Y		Y		Y																		All in working order
blinds/curtains																							
lights/power points	N		Y		Y																		Dust buildup noted, otherwise serviceable
skirting boards	N		Y		Y																		Dust buildup noted, otherwise serviceable
floor coverings	N		N		Y																		Visible wear across the main walkway
other																							
Dining room																							
walls/picture hooks	N		N		Y																		Plaster scraped near the edge, hooks displaced

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

Insert Y/3= Yes

Insert N/7= No

Tenant/s

Comments (if any)

Lessor/agent

Comment on tenant/s report

		n a e i C	d e g a m a d n U	g n i k r g W	n o t i c e d		
doors/doorway frames	N	Y	Y				Dust buildup noted, otherwise serviceable
ceiling/light fittings	Y	Y	Y				All in working order
blinds/curtains							
lights/power points	N	Y	Y				Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y				Visible wear across the main walkway
other							
Kitchen							
walls/picture hooks	N	N	Y				Plaster scraped near the edge, hooks displaced
cupboards/drawers	N	Y	Y				Dust buildup noted, otherwise serviceable
bench tops	N	Y	Y				Dust buildup noted, otherwise serviceable
sink/taps	N	Y	Y				Dust buildup noted, otherwise serviceable
stove/hotplates	N	Y	Y				Dust buildup noted, otherwise serviceable
oven/griller	N	Y	Y				Dust buildup noted, otherwise serviceable
range hood/exhaust fan	N	Y	Y				Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y				Visible wear across the main walkway
other							
Bedroom 1							
walls/picture hooks	N	N	Y				Plaster scraped near the edge, hooks displaced
wardrobe/shelves	N	Y	Y				Dust buildup noted, otherwise serviceable
windows/screens	N	Y	Y				Dust buildup noted, otherwise serviceable
blinds/curtains							
lights/power points	N	Y	Y				Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y				Visible wear across the main walkway
other							

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

Insert Y/3= Yes

Insert $N/7 = \text{No}$

Tenant/s

Comments (if any)

Lessor/agent

Comment on tenant/s report

[illegible]

Insert Y/3= Yes		Insert N/7= No		Tenant/s Comments (if any)		Lessor/agent Comment on tenant/s report
clothesline	N	Y	Y			Dust buildup noted, otherwise serviceable
garbage bins	N	Y	Y			Dust buildup noted, otherwise serviceable
external television antenna/tv points	N	Y	Y			Dust buildup noted, otherwise serviceable
other						
Balcony						
walls/railings	N	Y	Y			Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y			Visible wear across the main walkway
lights/power points	N	Y	Y			Dust buildup noted, otherwise serviceable
other						