

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

How to complete this report

1. Three copies of this condition report should be completed and signed by the landlord or the landlord's agent.

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

(b) At the end of the tenancy, the premises will be inspected and the condition compared to that stated in the original condition report.

(d) A condition report must be filled out whether or not a rental bond is paid.

Address of the premises

12/45 Wattle Grove

Riverstone, NSW

2765

Full name/s of the tenant/s

Marcus Ellery

Name of the lessor/agent

Owen Brackley - Meridian Property Group

The tenant/s received a copy of this report on (date):

Minimum Standards

The landlord must indicate whether the following apply to the residential premises:

Are the premises structurally sound?	☒	Yes	☐	No
Does the premises have adequate ventilation?	☒	Yes	☐	No
Does the premises have adequate plumbing and drainage?	☒	Yes	☐	No
Are there any signs of mould and dampness?	☐	Yes	☒	No
Are there any pests and vermin?	☐	Yes	☒	No
Have smoke alarms been installed in the residential premises?	☒	Yes	☐	No
Does the tenant agree with all of the above?	☐	Yes	☐	No

Insert Y/3= Yes

Insert N/7= No

Tenant/s
Comments (if any)

Lessor/agent
Comment on tenant/s report

C	n	d	g	g	n
e	a	e	a	n	i
i	e	m	a	k	r
	n	d	n	r	o
	U	W		o	W

Entrance/hall						
front door/screen door /security door	N	Y	Y			Dust buildup noted, otherwise serviceable
walls/picture hooks	N	N	Y		Marks were already there at move-in, noted on the entry report	Plaster scraped near the edge, hooks displaced
doorway frames	N	Y	Y			Dust buildup noted, otherwise serviceable
windows/screens/ window safety devices						
ceiling/light fittings	Y	Y	Y			All in working order
blinds/curtains						
lights/power points/ door bell	N	Y	Y			Dust buildup noted, otherwise serviceable
skirting boards	N	Y	Y			Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years	Visible wear across the main walkway
other						
Lounge room						
walls/picture hooks	N	N	Y		Marks were already there at move-in, noted on the entry report	Plaster scraped near the edge, hooks displaced
doors/doorway frames	N	Y	Y			Dust buildup noted, otherwise serviceable
windows/screens/ window safety devices						
ceiling/light fittings	Y	Y	Y			All in working order
blinds/curtains						
lights/power points	N	Y	Y			Dust buildup noted, otherwise serviceable
skirting boards	N	Y	Y			Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years	Visible wear across the main walkway
other						
Dining room						
walls/picture hooks	N	N	Y		Marks were already there at move-in, noted on the entry report	Plaster scraped near the edge, hooks displaced

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

Insert Y/3= Yes

Insert N/7= No

Tenant/s

Comments (if any)

Lessor/agent

Comment on tenant/s report

		n a e i C	d e g a m a d n U	g n i k r o W	n o r m a l u s e		
doors/doorway frames	N	Y	Y				Dust buildup noted, otherwise serviceable
ceiling/light fittings	Y	Y	Y				All in working order
blinds/curtains							
lights/power points	N	Y	Y				Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years		Visible wear across the main walkway
other							
Kitchen							
walls/picture hooks	N	N	Y		Marks were already there at move-in, noted on the entry report		Plaster scraped near the edge, hooks displaced
cupboards/drawers	N	Y	Y				Dust buildup noted, otherwise serviceable
bench tops	N	Y	Y				Dust buildup noted, otherwise serviceable
sink/taps	N	Y	Y				Dust buildup noted, otherwise serviceable
stove/hotplates	N	Y	Y				Dust buildup noted, otherwise serviceable
oven/griller	N	Y	Y				Dust buildup noted, otherwise serviceable
range hood/exhaust fan	N	Y	Y				Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years		Visible wear across the main walkway
other							
Bedroom 1							
walls/picture hooks	N	N	Y		Marks were already there at move-in, noted on the entry report		Plaster scraped near the edge, hooks displaced
wardrobe/shelves	N	Y	Y				Dust buildup noted, otherwise serviceable
windows/screens	N	Y	Y				Dust buildup noted, otherwise serviceable
blinds/curtains							
lights/power points	N	Y	Y				Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years		Visible wear across the main walkway
other							

Insert Y/3= Yes

Insert N/7= No

Tenant/s
Comments (if any)

Lessor/agent
Comment on tenant/s report

	clean	degreased	gunked	noticed		
Bathroom						
walls/tiling	N	Y	Y			Dust buildup noted, otherwise serviceable
bath/taps	N	Y	Y			Dust buildup noted, otherwise serviceable
shower/screen	N	Y	Y			Dust buildup noted, otherwise serviceable
basin/taps	N	Y	Y			Dust buildup noted, otherwise serviceable
mirror/cabinet	N	Y	Y			Dust buildup noted, otherwise serviceable
toilet/cistern/seat	N	Y	Y			Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years	Visible wear across the main walkway
other						
Laundry						
walls/tiling	N	Y	Y			Dust buildup noted, otherwise serviceable
tub/taps	N	Y	Y			Dust buildup noted, otherwise serviceable
washing machine taps	N	Y	Y			Dust buildup noted, otherwise serviceable
blinds/curtains						
floor coverings	N	N	Y		Wear is from normal use over three years	Visible wear across the main walkway
other						
Security/Safety						
locks/keys	N	Y	Y			Dust buildup noted, otherwise serviceable
smoke alarms	N	Y	Y			Dust buildup noted, otherwise serviceable
window safety devices	N	Y	Y			Dust buildup noted, otherwise serviceable
other						
General						
hot water system	N	Y	Y			Dust buildup noted, otherwise serviceable
gutters/downpipes	N	Y	Y			Dust buildup noted, otherwise serviceable

Insert Y/3= Yes		Insert N/7= No		Tenant/s Comments (if any)		Lessor/agent Comment on tenant/s report
clothesline	N	Y	Y			Dust buildup noted, otherwise serviceable
garbage bins	N	Y	Y			Dust buildup noted, otherwise serviceable
external television antenna/tv points	N	Y	Y			Dust buildup noted, otherwise serviceable
other						
Balcony						
walls/railings	N	Y	Y			Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years	Visible wear across the main walkway
lights/power points	N	Y	Y			Dust buildup noted, otherwise serviceable
other						