

Entry condition report: 12/45 Wattle Grove, Riverstone, NSW

How to complete this report

1. Three copies of this condition report should be completed and signed by the landlord or the landlord's agent.

Entry condition report: 12/45 Wattle Grove, Riverstone, NSW

(b) At the end of the tenancy, the premises will be inspected and the condition compared to that stated in the original condition report.

(d) A condition report must be filled out whether or not a rental bond is paid.

Address of the premises

12/45 Wattle Grove

Riverstone, NSW

2765

Full name/s of the tenant/s

Marcus Ellery

Name of the lessor/agent

Dana Whitfield - Kingsford Realty (Riverstone)

The tenant/s received a copy of this report on (date):

14

/

03

/ 2025

Minimum Standards

The landlord must indicate whether the following apply to the residential premises:

Are the premises structurally sound?

☒

 Yes

☐

 No

Does the premises have adequate ventilation?

☒

 Yes

☐

 No

Does the premises have adequate plumbing and drainage?

☒

 Yes

☐

 No

Are there any signs of mould and dampness?

☐

 Yes

☒

 No

Are there any pests and vermin?

☐

 Yes

☒

 No

Have smoke alarms been installed in the residential premises?

☒

 Yes

☐

 No

Does the tenant agree with all of the above?

☐

 Yes

☐

 No

Insert Y/3= Yes

Insert N/7= No

Lessor/agent
Comments (if any)

Tenant/s
Comment on lessor/agent report

Entrance/hall	front door/screen door /security door	walls/picture hooks	doorway frames	windows/screens/ window safety devices	ceiling/light fittings	blinds/curtains	lights/power points/ door bell	skirting boards	floor coverings	other
Y	Y	Y			Y		Y	Y	Y	

Entrance/hall						
front door/screen door /security door	Y	Y	Y		Clean and in working order at handover	
walls/picture hooks	Y	Y	Y		Scuffed near the light switch, four picture hooks	
doorway frames	Y	Y	Y		Clean and in working order at handover	
windows/screens/ window safety devices						
ceiling/light fittings	Y	Y	Y		Two oyster lights, one smoke alarm	
blinds/curtains						
lights/power points/ door bell	Y	Y	Y		Clean and in working order at handover	
skirting boards	Y	Y	Y		Clean and in working order at handover	
floor coverings	Y	N	Y		Small gap in the boards by the doorway	
other						
Lounge room						
walls/picture hooks	Y	Y	Y		Scuffed near the light switch, four picture hooks	
doors/doorway frames	Y	Y	Y		Clean and in working order at handover	
windows/screens/ window safety devices						
ceiling/light fittings	Y	Y	Y		Two oyster lights, one smoke alarm	
blinds/curtains						
lights/power points	Y	Y	Y		Clean and in working order at handover	
skirting boards	Y	Y	Y		Clean and in working order at handover	
floor coverings	Y	N	Y		Small gap in the boards by the doorway	
other						
Dining room						
walls/picture hooks	Y	Y	Y		Scuffed near the light switch, four picture hooks	

Entry condition report: 12/45 Wattle Grove, Riverstone, NSW

Insert Y/3= Yes

Insert N/7= No

Lessor/agent
Comments (if any)

Tenant/s
Comment on lessor/agent report

	n a e i C	d e g a m a d n U	g n i k r o W	n o t c o m m e n t s		
doors/doorway frames	Y	Y	Y		Clean and in working order at handover	
ceiling/light fittings	Y	Y	Y		Two oyster lights, one smoke alarm	
blinds/curtains						
lights/power points	Y	Y	Y		Clean and in working order at handover	
floor coverings	Y	N	Y		Small gap in the boards by the doorway	
other						
Kitchen						
walls/picture hooks	Y	Y	Y		Scuffed near the light switch, four picture hooks	
cupboards/drawers	Y	Y	Y		Clean and in working order at handover	
bench tops	Y	Y	Y		Clean and in working order at handover	
sink/taps	Y	Y	Y		Clean and in working order at handover	
stove/hotplates	Y	Y	Y		Clean and in working order at handover	
oven/griller	Y	Y	Y		Clean and in working order at handover	
range hood/exhaust fan	Y	Y	Y		Clean and in working order at handover	
floor coverings	Y	N	Y		Small gap in the boards by the doorway	
other						
Bedroom 1						
walls/picture hooks	Y	Y	Y		Scuffed near the light switch, four picture hooks	
wardrobe/shelves	Y	Y	Y		Clean and in working order at handover	
windows/screens	Y	Y	Y		Clean and in working order at handover	
blinds/curtains						
lights/power points	Y	Y	Y		Clean and in working order at handover	
floor coverings	Y	N	Y		Small gap in the boards by the doorway	
other						

Entry condition report: 12/45 Wattle Grove, Riverstone, NSW

Insert Y/3= Yes

Insert N/7= No


Lessor/agent
Comments (if any)

Tenant/s
Comment on lessor/agent report


	nae i C	d e g a m a d n U	g n i k r o W	noe-ee		
Bathroom						
walls/tiling	Y	Y	Y		Clean and in working order at handover	
bath/taps	Y	Y	Y		Clean and in working order at handover	
shower/screen	Y	Y	Y		Clean and in working order at handover	
basin/taps	Y	Y	Y		Clean and in working order at handover	
mirror/cabinet	Y	Y	Y		Clean and in working order at handover	
toilet/cistern/seat	Y	Y	Y		Clean and in working order at handover	
floor coverings	Y	N	Y		Small gap in the boards by the doorway	
other						
Laundry						
walls/tiling	Y	Y	Y		Clean and in working order at handover	
tub/taps	Y	Y	Y		Clean and in working order at handover	
washing machine taps	Y	Y	Y		Clean and in working order at handover	
blinds/curtains						
floor coverings	Y	N	Y		Small gap in the boards by the doorway	
other						
Security/Safety						
locks/keys	Y	Y	Y		Clean and in working order at handover	
smoke alarms	Y	Y	Y		Clean and in working order at handover	
window safety devices	Y	Y	Y		Clean and in working order at handover	
other						
General						
hot water system	Y	Y	Y		Clean and in working order at handover	
gutters/downpipes	Y	Y	Y		Clean and in working order at handover	

Insert Y/3= Yes		Insert N/7= No		Lessor/agent Comments (if any)		Tenant/s Comment on lessor/agent report
		n a e i C	d e g a m a d n U	g n i k r o W	n o t c o m m e n t e d	
clothesline	Y	Y	Y		Clean and in working order at handover	
garbage bins	Y	Y	Y		Clean and in working order at handover	
external television antenna/tv points	Y	Y	Y		Clean and in working order at handover	
other						
Balcony						
walls/railings	Y	Y	Y		Clean and in working order at handover	
floor coverings	Y	N	Y		Small gap in the boards by the doorway	
lights/power points	Y	Y	Y		Clean and in working order at handover	
other						


Condition report - Photos




Entrance/hall (Agent) - 1 of 6




Entrance/hall (Agent) - 2 of 6




Entrance/hall (Agent) - 3 of 6



Entrance/hall (Agent) - 4 of 6




Entrance/hall (Agent) - 5 of 6




Entrance/hall (Agent) - 6 of 6


Condition report - Photos




Kitchen (Agent) - 1 of 6




Kitchen (Agent) - 2 of 6




Kitchen (Agent) - 3 of 6



Kitchen (Agent) - 4 of 6



Kitchen (Agent) - 5 of 6



Kitchen (Agent) - 6 of 6