

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

How to complete this report

1. Three copies of this condition report should be completed and signed by the landlord or the landlord's agent.

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

(b) At the end of the tenancy, the premises will be inspected and the condition compared to that stated in the original condition report.

(d) A condition report must be filled out whether or not a rental bond is paid.

Address of the premises

12/45 Wattle Grove

Riverstone, NSW

2765

Full name/s of the tenant/s

Marcus Ellery

Name of the lessor/agent

Owen Brackley - Meridian Property Group

The tenant/s received a copy of this report on (date):

Minimum Standards

The landlord must indicate whether the following apply to the residential premises:

Are the premises structurally sound?	☒ Yes	☐ No
Does the premises have adequate ventilation?	☒ Yes	☐ No
Does the premises have adequate plumbing and drainage?	☒ Yes	☐ No
Are there any signs of mould and dampness?	☐ Yes	☒ No
Are there any pests and vermin?	☐ Yes	☒ No
Have smoke alarms been installed in the residential premises?	☒ Yes	☐ No
Does the tenant agree with all of the above?	☐ Yes	☐ No

Insert Y/3= Yes

Insert N/7= No

Tenant/s
Comments (if any)

Lessor/agent
Comment on tenant/s report

C	n	a	e	i	C	d	e	g	a	m	a	d	n	U	g	n	i	k	r	o	W	n	e	a	r	-	n	e	s
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Entrance/hall									
front door/screen door /security door	N	Y	Y			Dust buildup noted, otherwise serviceable			
walls/picture hooks	N	N	Y		Marks were already there at move-in, noted on the entry report	Plaster scraped near the edge, hooks displaced			
doorway frames	N	Y	Y			Dust buildup noted, otherwise serviceable			
windows/screens/ window safety devices									
ceiling/light fittings	Y	Y	Y			All in working order			
blinds/curtains									
lights/power points/ door bell	N	Y	Y			Dust buildup noted, otherwise serviceable			
skirting boards	N	Y	Y			Dust buildup noted, otherwise serviceable			
floor coverings	N	N	Y		Wear is from normal use over three years	Visible wear across the main walkway			
other									
Lounge room									
walls/picture hooks	N	N	Y		Marks were already there at move-in, noted on the entry report	Plaster scraped near the edge, hooks displaced			
doors/doorway frames	N	Y	Y			Dust buildup noted, otherwise serviceable			
windows/screens/ window safety devices									
ceiling/light fittings	Y	Y	Y			All in working order			
blinds/curtains									
lights/power points	N	Y	Y			Dust buildup noted, otherwise serviceable			
skirting boards	N	Y	Y			Dust buildup noted, otherwise serviceable			
floor coverings	N	N	Y		Wear is from normal use over three years	Visible wear across the main walkway			
other									
Dining room									
walls/picture hooks	N	N	Y		Marks were already there at move-in, noted on the entry report	Plaster scraped near the edge, hooks displaced			

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

Insert Y/3= Yes

Insert N/7= No

Tenant/s

Comments (if any)

Lessor/agent

Comment on tenant/s report

		n a e i C	d e g a m a d n U	g n i k r o W	n o r m a l u s e		
doors/doorway frames	N	Y	Y				Dust buildup noted, otherwise serviceable
ceiling/light fittings	Y	Y	Y				All in working order
blinds/curtains							
lights/power points	N	Y	Y				Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years		Visible wear across the main walkway
other							
Kitchen							
walls/picture hooks	N	N	Y		Marks were already there at move-in, noted on the entry report		Plaster scraped near the edge, hooks displaced
cupboards/drawers	N	Y	Y				Dust buildup noted, otherwise serviceable
bench tops	N	Y	Y				Dust buildup noted, otherwise serviceable
sink/taps	N	Y	Y				Dust buildup noted, otherwise serviceable
stove/hotplates	N	Y	Y				Dust buildup noted, otherwise serviceable
oven/griller	N	Y	Y				Dust buildup noted, otherwise serviceable
range hood/exhaust fan	N	Y	Y				Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years		Visible wear across the main walkway
other							
Bedroom 1							
walls/picture hooks	N	N	Y		Marks were already there at move-in, noted on the entry report		Plaster scraped near the edge, hooks displaced
wardrobe/shelves	N	Y	Y				Dust buildup noted, otherwise serviceable
windows/screens	N	Y	Y				Dust buildup noted, otherwise serviceable
blinds/curtains							
lights/power points	N	Y	Y				Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years		Visible wear across the main walkway
other							

Exit condition report: 12/45 Wattle Grove, Riverstone, NSW

Insert Y/3= Yes

Insert $N/7 = N_0$

Tenant/s

Comments (if any)


Lessor/agent

Comment on tenant/s report


	C	U	N	D	W	O	S
	n	d	g	n	s		
	a	e	a	i	c		
	e	r	m	k	t		
	r	r	a	r	r		
	y	y	d	r	e		
	w	o	n	o	s		
Bathroom							
walls/tiling	N	Y	Y			Dust buildup noted, otherwise serviceable	
bath/taps	N	Y	Y			Dust buildup noted, otherwise serviceable	
shower/screen	N	Y	Y			Dust buildup noted, otherwise serviceable	
basin/taps	N	Y	Y			Dust buildup noted, otherwise serviceable	
mirror/cabinet	N	Y	Y			Dust buildup noted, otherwise serviceable	
toilet/cistern/seal	N	Y	Y			Dust buildup noted, otherwise serviceable	
floor coverings	N	N	Y		Wear is from normal use over three years	Visible wear across the main walkway	
other							
Laundry							
walls/tiling	N	Y	Y			Dust buildup noted, otherwise serviceable	
tub/taps	N	Y	Y			Dust buildup noted, otherwise serviceable	
washing machine taps	N	Y	Y			Dust buildup noted, otherwise serviceable	
blinds/curtains							
floor coverings	N	N	Y		Wear is from normal use over three years	Visible wear across the main walkway	
other							
Security/Safety							
locks/keys	N	Y	Y			Dust buildup noted, otherwise serviceable	
smoke alarms	N	Y	Y			Dust buildup noted, otherwise serviceable	
window safety devices	N	Y	Y			Dust buildup noted, otherwise serviceable	
other							
General							
hot water system	N	Y	Y			Dust buildup noted, otherwise serviceable	
gutters/downpipes	N	Y	Y			Dust buildup noted, otherwise serviceable	

Insert Y/3= Yes		Insert N/7= No		Tenant/s Comments (if any)		Lessor/agent Comment on tenant/s report
clothesline	N	Y	Y			Dust buildup noted, otherwise serviceable
garbage bins	N	Y	Y			Dust buildup noted, otherwise serviceable
external television antenna/tv points	N	Y	Y			Dust buildup noted, otherwise serviceable
other						
Balcony						
walls/railings	N	Y	Y			Dust buildup noted, otherwise serviceable
floor coverings	N	N	Y		Wear is from normal use over three years	Visible wear across the main walkway
lights/power points	N	Y	Y			Dust buildup noted, otherwise serviceable
other						


Condition report - Photos




Entrance/hall (Agent) - 1 of 6




Entrance/hall (Agent) - 2 of 6




Entrance/hall (Agent) - 3 of 6



Entrance/hall (Agent) - 4 of 6




Entrance/hall (Agent) - 5 of 6




Entrance/hall (Agent) - 6 of 6


Condition report - Photos




Kitchen (Agent) - 1 of 6




Kitchen (Agent) - 2 of 6




Kitchen (Agent) - 3 of 6



Kitchen (Agent) - 4 of 6



Kitchen (Agent) - 5 of 6



Kitchen (Agent) - 6 of 6