DEVELOPMENT SAMPLE - NOT A CERTIFICATE

Commissioning & Quality Review

Sample handover evidence for the TRISE customer portal workflow.

Project	Green Heights Community - 2-lift installation demo
Site	Green Heights Community, Bengaluru
Elevator	ELP05 Browser Lift 1
Equipment	Passenger traction elevator
Review date	29 October 2026
Report status	Development sample for workflow verification

Review checklist

Inspection item	Sample result
Door operation	PASS - sample entry
Travel and leveling	PASS - sample entry
Emergency alarm	PASS - sample entry
Safety circuit review	PASS - sample entry

Use limitation

This synthetic document exists only to test upload, customer visibility, handover review, and audit behavior in a local development environment. It is not an inspection record, safety certificate, or evidence of completed work.

Prepared for local application workflow testing