

CORRECTIVE MAINTENANCE WORK ORDER COMPLETION REPORT: P-194

1. Work Order Metadata

Work Order Number: WO-9412
Asset Tag: P-194
Completion Date: 2026-02-18
Technician: David Mercer (Senior Rotating Equipment Specialist)
Operating Hours: 3,200 hours
Status: Completed & Verified

2. Scope of Maintenance Executed

- Complete disassembly of pump bearing housing and seal chamber.
- Replaced Drive-End bearing with new SKF-6314-2Z deep groove ball bearing.
- Inspected Non-Drive-End SKF-NU-314 roller bearing (verified in excellent condition).
- Installed new BURG-M7N cartridge mechanical seal with Viton secondary elastomers.
- Flushed lube reservoir and charged with 4.5 liters of fresh ISO VG 46 turbine oil.
- Precision laser alignment completed with soft-foot check under 0.02 mm.

3. Sign-off & Quality Acceptance

Post-maintenance solo run and coupled run vibration measured 1.9 mm/s RMS.
Thermal stabilization reached 66 deg C after 4 hours continuous full-load run.
Signed off by Lead Mechanical Engineer.