



# **SERVICE CLAIM**

DEALER CODE		DEALER CLAIM NO		TEPS CODE		SALES MODEL NO		DELIVERY DDMMYY		PARTS START DDMMYY		REPAIR DATE DDMMYY	
J211		BB01247				6030 BH		16JUN15				17MAY18	
INITIAL DEALER		COVERAGE TYPE		PROD ID SERIAL NO		PRODUCT HR/MI/KM		PARTS HR/MI/KM		REPAIR HOURS			
CODE CLAIM NO				0DHL30304		15026 H		15026 H		2.00			
PART CAUSING FAILURE				DESC CODE		GROUP CONTAINING FAILED PART				8507838			
PART NO PS45780		PART NAME PS45780				GROUP NO. 56 7755		GROUP NAME COMPLETED PSP		DS851374979			
FINDINGS/COMMENTS				FOR DEALER USE									
SL.08FEB2018				PT. CIPTA KRIDATAMA									
RELATED EQUIPMENT			CUST.CREDIT%		IMPORT PERCENT		CLAIM AUTHO.NO.		POLICY CODE		CATERPILLAR CLAIM NO.		
MAKE AA	CAB	SERIAL NO 0DHL30304	PARTS 100.00	LABOR 100.00	PERCENT 23.80					L736464			
NON-CLAIMED DEALER EXPENSES													
REPAIR		TRAVEL		MILEAGE		OTHER AMOUNT		CURR CODE		DEC POS			
HOURS	AMOUNT	HOURS	AMOUNT	MI/KM	AMOUNT								
.00	.00	.00	.00	.00	.00	.00		.00		USD 2			
ID	QTY	PART NO	DESCRIPTION	DESC. CODE	RATE	TOTAL	CURR	DEC POS					
L	2.00	7000 023	REPAIR MACHINE			.00		.00 USD 2					
COMPLETED PERFORM PS45780 SL.08FEB2018 REV.09APR2018. UPDATING THE DRIVE CONTROLLER AND BOARD CONTROL SYSTEM SOFTWARE. TEST PERFORMANCED FOUND GOOD. ----- *)ONLY CLAIM LABOR 2 HOURS FOR UPDATING THE DRIVE. ===== [TW 28MAY2018]													
TOTAL CLAIM AMOUNT:						.00							
SETTLEMENTS:		SETTLEMENT NO		DATE		SETTLEMENT AMT							
		C86SC 952196		30/05/18		.00							
*** END OF REPORT ***													
CLAIMED DEALER EXPENSES (DEALER USE)													
PARTS		LABOR		TRAVEL		VEHICLE		MISC.		SETTLEMENT NOTICE			
.00		38.62				.00		.00		.00 C86SC 952196			
DEALERSHIP NAME				AUTHORIZED DEALER SIGNATURE(S)				DATE					
P.T. TRAKINDO UTAMA								28MAY18					
AUTHORIZER'S NAME				CLAIM AUTHORIZER'S SIGNATURE				DATE					

DEALER CLAIM COPY