



# SERVICE CLAIM

PRODUCT ABBREVIATION																																							
EM	TE	IE	ME	LT	PT	OT	X																																
DEALER CODE	DEALER CLAIM NO	TEPS CODE	SALES MODEL NO	DELIVERY DDMMYY	PARTS START DDMMYY	REPAIR DATE DDMMYY																																	
J211	BB01240		6030 BH		29NOV17	18MAY18																																	
INITIAL DEALER		COVERAGE TYPE	PROD ID SERIAL NO	PRODUCT HR/MI/KM	PARTS HR/MI/KM	REPAIR HOURS																																	
CODE	CLAIM NO		0DHL30303	14849 H	1984 H	1.00																																	
PART CAUSING FAILURE			DESC CODE	GROUP CONTAINING FAILED PART			8508044																																
PART NO	PART NAME		GROUP NO.	GROUP NAME			DS851375006																																
541-5911	BRUSH		13 7320	AIR CONDITIONER																																			
FINDINGS/COMMENTS			FOR DEALER USE																																				
PREMATURE WORN			PT. CIPTA KRIDATAMA																																				
RELATED EQUIPMENT		CUST.CREDIT%	IMPORT PERCENT	CLAIM AUTHO.NO.	POLICY CODE	CATERPILLAR CLAIM NO.																																	
MAKE	CAB	SERIAL NO	PARTS	LABOR																																			
AA		0DHL30303	100.00	100.00	23.80			L736612																															
NON-CLAIMED DEALER EXPENSES																																							
REPAIR		TRAVEL		MILEAGE		OTHER AMOUNT	CURR CODE	DEC POS																															
HOURS	AMOUNT	HOURS	AMOUNT	MI/KM	AMOUNT																																		
1.00	19.31	.00	.00	.00	.00	.00	.00	USD	2																														
<table border="1"> <thead> <tr> <th>ID</th> <th>QTY</th> <th>PART NO</th> <th>DESCRIPTION</th> <th>DESC. CODE</th> <th>RATE</th> <th>TOTAL</th> <th>CURR</th> <th>DEC POS</th> <th></th> </tr> </thead> <tbody> <tr> <td>P</td> <td>2.00</td> <td>541-5911</td> <td>BRUSH</td> <td></td> <td></td> <td>.01</td> <td></td> <td>.02</td> <td>USD 2</td> </tr> <tr> <td colspan="10"> ** WARRANTY PART MACHINE  PURCHASE REFF/DATE : 8506341 / 29NOV2017  DATE INSTALLED/SMU : 29NOV2017 / 12865 Hrs  DATE FAILED/SMU : 13MAY2018 / 14849 Hrs  PART LIFE : 1984 Hrs (LESS THAN 6 MONTHS)  PURCHASE DATA ATTACHED INTO SIMSI THROUGH WO NO:8508044.  COMPLAINT:  AC WAS HOT.  CAUSE OF FAILURE:  AFTER INSPECTING FOUND CARBON BRUSH PN.541-5911 AT PO#2 HAD PREMATURE WORN.  CORRECTION:  REPLACED IT WITH NEW PARTS. TESTED FOUND GOOD.  -----  PLEASE DON'T TREAT THIS CLAIM AS DUPLICATE.[4TH FAILURE]  THIS IS REPEAT FAILURE OF 4870615 CABRON BRUSH PO2 ON SN DHL30303. HERE IS THE DETAIL:  *) FIRST FAILURE WO.8506341, THIS WO WAS WARRANTY START DATE SINCE CUSTOMER FULL PAID.  *) SECOND FAILURE WO.8506935, PART LIFE SHOULD BE 694 HRS.  *) THIRD FAILURE WO.8507938, PART LIFE SHOULD BE 148 HRS AND ALREADY USED CAT PN.541-5911. </td> </tr> </tbody> </table>										ID	QTY	PART NO	DESCRIPTION	DESC. CODE	RATE	TOTAL	CURR	DEC POS		P	2.00	541-5911	BRUSH			.01		.02	USD 2	** WARRANTY PART MACHINE PURCHASE REFF/DATE : 8506341 / 29NOV2017 DATE INSTALLED/SMU : 29NOV2017 / 12865 Hrs DATE FAILED/SMU : 13MAY2018 / 14849 Hrs PART LIFE : 1984 Hrs (LESS THAN 6 MONTHS) PURCHASE DATA ATTACHED INTO SIMSI THROUGH WO NO:8508044. COMPLAINT: AC WAS HOT. CAUSE OF FAILURE: AFTER INSPECTING FOUND CARBON BRUSH PN.541-5911 AT PO#2 HAD PREMATURE WORN. CORRECTION: REPLACED IT WITH NEW PARTS. TESTED FOUND GOOD. ----- PLEASE DON'T TREAT THIS CLAIM AS DUPLICATE.[4TH FAILURE] THIS IS REPEAT FAILURE OF 4870615 CABRON BRUSH PO2 ON SN DHL30303. HERE IS THE DETAIL: *) FIRST FAILURE WO.8506341, THIS WO WAS WARRANTY START DATE SINCE CUSTOMER FULL PAID. *) SECOND FAILURE WO.8506935, PART LIFE SHOULD BE 694 HRS. *) THIRD FAILURE WO.8507938, PART LIFE SHOULD BE 148 HRS AND ALREADY USED CAT PN.541-5911.									
ID	QTY	PART NO	DESCRIPTION	DESC. CODE	RATE	TOTAL	CURR	DEC POS																															
P	2.00	541-5911	BRUSH			.01		.02	USD 2																														
** WARRANTY PART MACHINE PURCHASE REFF/DATE : 8506341 / 29NOV2017 DATE INSTALLED/SMU : 29NOV2017 / 12865 Hrs DATE FAILED/SMU : 13MAY2018 / 14849 Hrs PART LIFE : 1984 Hrs (LESS THAN 6 MONTHS) PURCHASE DATA ATTACHED INTO SIMSI THROUGH WO NO:8508044. COMPLAINT: AC WAS HOT. CAUSE OF FAILURE: AFTER INSPECTING FOUND CARBON BRUSH PN.541-5911 AT PO#2 HAD PREMATURE WORN. CORRECTION: REPLACED IT WITH NEW PARTS. TESTED FOUND GOOD. ----- PLEASE DON'T TREAT THIS CLAIM AS DUPLICATE.[4TH FAILURE] THIS IS REPEAT FAILURE OF 4870615 CABRON BRUSH PO2 ON SN DHL30303. HERE IS THE DETAIL: *) FIRST FAILURE WO.8506341, THIS WO WAS WARRANTY START DATE SINCE CUSTOMER FULL PAID. *) SECOND FAILURE WO.8506935, PART LIFE SHOULD BE 694 HRS. *) THIRD FAILURE WO.8507938, PART LIFE SHOULD BE 148 HRS AND ALREADY USED CAT PN.541-5911.																																							
CLAIMED DEALER EXPENSES (DEALER USE)																																							
PARTS	LABOR	TRAVEL	VEHICLE	MISC.	SETTLEMENT NOTICE																																		
147.92	.00	.00	.00	.00	.00																																		
DEALERSHIP NAME		AUTHORIZED DEALER SIGNATURE(S)					DATE																																
P.T. TRAKINDO UTAMA							28MAY18																																
AUTHORIZER'S NAME		CLAIM AUTHORIZER'S SIGNATURE					DATE																																

DEALER CLAIM COPY



# **SERVICE CLAIM**

PRODUCT ABBREVIATION																																																																								
EM	TE	IE	ME	LT	PT	OT	X																																																																	
DEALER CODE	DEALER CLAIM NO		TEPS CODE	SALES MODEL NO		DELIVERY DDMMYY		PARTS START DDMMYY		REPAIR DATE DDMMYY																																																														
J211	BB01240			6030 BH		29NOV17		18MAY18																																																																
INITIAL DEALER			COVERAGE TYPE	PROD ID SERIAL NO	PRODUCT HR/MI/KM	PARTS HR/MI/KM	REPAIR HOURS																																																																	
CODE	CLAIM NO																																																																							
				0DHL30303	14849 H	1984 H 1.00																																																																		
PART CAUSING FAILURE				DESC CODE	GROUP CONTAINING FAILED PART				8508044																																																															
PART NO 541-5911		PART NAME BRUSH			GROUP NO. 13 7320		GROUP NAME AIR CONDITIONER		DS851375006																																																															
FINDINGS/COMMENTS PREMATURE WORN				FOR DEALER USE PT. CIPTA KRIDATAMA																																																																				
RELATED EQUIPMENT			CUST.CREDIT%		IMPORT PERCENT	CLAIM AUTHO.NO.	POLICY CODE	CATERPILLAR CLAIM NO.																																																																
MAKE AA	CAB	SERIAL NO 0DHL30303	PARTS 100.00	LABOR 100.00	23.80			L736612																																																																
NON-CLAIMED DEALER EXPENSES																																																																								
REPAIR		TRAVEL		MILEAGE		OTHER AMOUNT	CURR CODE	DEC POS																																																																
HOURS	AMOUNT	HOURS	AMOUNT	MI/KM	AMOUNT																																																																			
1.00	19.31	.00	.00	.00	.00	.00	.00	USD	2																																																															
<table border="1"> <thead> <tr> <th>ID</th> <th>QTY</th> <th>PART NO</th> <th>DESCRIPTION</th> <th>DESC. CODE</th> <th>RATE</th> <th>TOTAL</th> <th>CURR</th> <th>DEC POS</th> </tr> </thead> <tbody> <tr> <td colspan="9">=====</td> </tr> <tr> <td colspan="9">[TW 28MAY2018]</td> </tr> <tr> <td colspan="8">TOTAL CLAIM AMOUNT:</td> <td>.01</td> </tr> <tr> <td colspan="9"> <table border="1"> <thead> <tr> <th>SETTLEMENTS:</th> <th>SETTLEMENT NO</th> <th>DATE</th> <th>SETTLEMENT AMT</th> </tr> </thead> <tbody> <tr> <td></td> <td>C86SC 952454</td> <td>31/05/18</td> <td>.00</td> </tr> </tbody> </table> </td> </tr> <tr> <td colspan="9">*** END OF REPORT ***</td> </tr> </tbody> </table>											ID	QTY	PART NO	DESCRIPTION	DESC. CODE	RATE	TOTAL	CURR	DEC POS	=====									[TW 28MAY2018]									TOTAL CLAIM AMOUNT:								.01	<table border="1"> <thead> <tr> <th>SETTLEMENTS:</th> <th>SETTLEMENT NO</th> <th>DATE</th> <th>SETTLEMENT AMT</th> </tr> </thead> <tbody> <tr> <td></td> <td>C86SC 952454</td> <td>31/05/18</td> <td>.00</td> </tr> </tbody> </table>									SETTLEMENTS:	SETTLEMENT NO	DATE	SETTLEMENT AMT		C86SC 952454	31/05/18	.00	*** END OF REPORT ***								
ID	QTY	PART NO	DESCRIPTION	DESC. CODE	RATE	TOTAL	CURR	DEC POS																																																																
=====																																																																								
[TW 28MAY2018]																																																																								
TOTAL CLAIM AMOUNT:								.01																																																																
<table border="1"> <thead> <tr> <th>SETTLEMENTS:</th> <th>SETTLEMENT NO</th> <th>DATE</th> <th>SETTLEMENT AMT</th> </tr> </thead> <tbody> <tr> <td></td> <td>C86SC 952454</td> <td>31/05/18</td> <td>.00</td> </tr> </tbody> </table>									SETTLEMENTS:	SETTLEMENT NO	DATE	SETTLEMENT AMT		C86SC 952454	31/05/18	.00																																																								
SETTLEMENTS:	SETTLEMENT NO	DATE	SETTLEMENT AMT																																																																					
	C86SC 952454	31/05/18	.00																																																																					
*** END OF REPORT ***																																																																								
CLAIMED DEALER EXPENSES (DEALER USE)																																																																								
PARTS	LABOR	TRAVEL	VEHICLE	MISC.	SETTLEMENT NOTICE																																																																			
147.92	.00	.00	.00	.00	.00 C86SC 952454																																																																			
DEALERSHIP NAME			AUTHORIZED DEALER SIGNATURE(S)					DATE																																																																
P.T. TRAKINDO UTAMA								28MAY18																																																																
AUTHORIZER'S NAME			CLAIM AUTHORIZER'S SIGNATURE					DATE																																																																

DEALER CLAIM COPY