Handover inspection

Testgasse 7, Top 4, 1050 Vienna · 2 October 2026 · Inspector: Anna Berger

Room	Condition	Notes
Living room	Good	Parquet sanded 2025, no damage
Kitchen	Good	All appliances working
Bathroom	Fair	Grout worn around the bath
Bedroom	Needs work	Damp patch at the window, see photo
Hall	Good	Fuse box labelled



Photo 1: damp patch with mould at the bedroom window (north side).

Meter readings and keys

Electricity: 48,213.7 kWh (meter 1EMH0012345)

Gas: 7,904.2 m³

Cold water: 312.45 m³

Keys handed over: 3 flat, 2 building, 1 letterbox

Signed by tenant and landlord on 2 October 2026.