




Move In Inspection

106 - Flats, Cerise 106, 106 Cerise, Ridge Close, Stone Gate Estate, Stone Ridge, 0157

February 26th 2026 11:00 SAST

Prepared By Bernice Barnard

Contents

Actions 2

Areas 3

 Living Room/ Lounge/ Open Plan 3

 Kitchen 7

 Passage 17

 Bedroom 1 / Main Bedroom 19

 Bedroom 2 24

 Bathroom 29

 Patio 39

 Keys 41




Declaration 42

Appendix 43

 Comment Summary 43

 Status Overview 43

Actions Required				
Ref	Action Required	Responsibility	Comments	Price
3.4 Passage » Walls / Paint : Right	Needs Maintenance	Investigate	Wall was not properly painted by the contractor. 2x white touch-up marks visible	
8.2 Keys » Remotes/Discs	Needs Maintenance	Landlord		
Total				R 0,00



1. LIVING ROOM/ LOUNGE/ OPEN PLAN					
Ref	Name	Answers		Comments	Additional Comments
1.1	Doors/ Sliding Door	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
1.2	Door Frame	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
1.3	Stricker Plate	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
1.4	Lock and Keys	Clean:	Yes	New night latch  keys	
		Undamaged:	Yes		
		Working:	Yes		
1.5	Security Gates	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
1.6	Security Gate Lock and Keys	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
1.7	Ceiling & Cornice	Clean:	Yes		
		Undamaged:	Yes		
1.8	Light Fittings / Cover	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
1.9	Light Switches	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		

1. LIVING ROOM/ LOUNGE/ OPEN PLAN (CONT.)


1.10	Bulbs	Clean: Yes Undamaged: Yes Working: Yes	No electricity	
1.11	Curtains/Curtain Rail/Blinds	Clean: Yes Undamaged: Yes Working: Yes		
1.12	Walls / Paint : Front	Clean: Yes Undamaged: Yes	Clean without any nails	
1.13	Walls / Paint : Left	Clean: Yes Undamaged: Yes	Clean without any nails	
1.14	Walls / Paint : Right	Clean: Yes Undamaged: Yes	Clean without any nails	
1.15	Electrical Sockets	Clean: Yes Undamaged: Yes Working: Yes		
1.16	Floor/Carpets/ Tiles	Clean: Yes Undamaged: No	Hairline cracks over floor tiles	
1.17	Skirting / Tile / Wooden	Clean: Yes Undamaged: Yes		
1.18	DSTV Connection	Clean: Yes Undamaged: Yes Working: Yes		
1.19	DB Board	Clean: Yes Undamaged: No Working: Yes	DB Board cover missing	
1.20	IMB and Dish	Clean: Yes Undamaged: Yes Working: Yes		

1. LIVING ROOM/ LOUNGE/ OPEN PLAN (CONT.)




26 Feb 2026 10:10

Ref #1



26 Feb 2026 10:10

Ref #1



26 Feb 2026 10:10

Ref #1



26 Feb 2026 10:10

Ref #1




26 Feb 2026 10:06

Ref #1.1



26 Feb 2026 10:06

Ref #1.1



26 Feb 2026 10:06

Ref #1.5



26 Feb 2026 10:06

Ref #1.5



26 Feb 2026 10:06

Ref #1.7



26 Feb 2026 10:07

Ref #1.8



26 Feb 2026 10:07

Ref #1.9



26 Feb 2026 10:08







Ref #1.11




26 Feb 2026 10:08

Ref #1.11

1. LIVING ROOM/ LOUNGE/ OPEN PLAN (CONT.)



1. LIVING ROOM/ LOUNGE/ OPEN PLAN (CONT.)






2. KITCHEN

Ref	Name	Answers	Comments	Additional Comments
2.1	Doors	Clean: Yes Undamaged: Yes Working: Yes		
2.2	Door Frame	Clean: Yes Undamaged: Yes Working: Yes		
2.3	Striker Plate	Clean: Yes Undamaged: Yes Working: Yes		
2.4	Lock and Keys	Clean: Yes Undamaged: Yes Working: Yes		

2. KITCHEN (CONT.)					
2.5	Security Gates	Clean:	Yes	Newly painted gate	
		Undamaged:	Yes		
		Working:	Yes		
2.6	Security Gate Lock and Keys	Clean:	Yes	Newly painted gate	
		Undamaged:	Yes		
		Working:	Yes		
2.7	Ceiling & Cornice	Clean:	Yes		
		Undamaged:	Yes		
2.8	Light Fittings / Cover	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
2.9	Light Switches	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
2.10	Bulbs	Clean:	Yes	No electricity	
		Undamaged:	Yes		
		Working:	Yes		
2.11	Curtains/Curtain Rail/Blinds	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
2.12	Window Panes	Clean:	Yes	Outside window frame clean	
		Undamaged:	Yes		
		Working:	Yes		
2.13	Windows Frames	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
2.14	Window Catches / Stay/ Latches	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		

2. KITCHEN (CONT.)					
2.15	Walls / Paint : Back	Clean: Yes Undamaged: Yes			
2.16	Walls / Paint : Left	Clean: Yes Undamaged: Yes			
2.17	Walls / Paint : Right	Clean: Yes Undamaged: Yes			
2.18	Electrical Sockets and Switches	Clean: Yes Undamaged: Yes Working: Yes			
2.19	Extractor Fan	Clean: Yes Undamaged: Yes Working: Yes			
2.20	Oven	Clean: Yes Undamaged: Yes Working: Yes			
2.21	Oven Door	Clean: Yes Undamaged: Yes Working: Yes	1x oven rack 1z oven pan		
2.22	Oven Light	Clean: Yes Undamaged: Yes Working: Yes			
2.23	Hob and Knobs	Clean: Yes Undamaged: Yes Working: Yes			
2.24	Sink/Taps/Plug	Clean: Yes Undamaged: Yes Working: Yes			

2. KITCHEN (CONT.)				
2.25	Countertops	Clean: Yes Undamaged: Yes		
2.26	Cupboards Doors	Clean: Yes Undamaged: Yes Working: Yes		
2.27	Cupboard Shelves	Clean: Yes Undamaged: Yes		
2.28	Cupboard Handles and Hindges	Clean: Yes Undamaged: Yes Working: Yes		
2.29	Cupboard Kick Board	Clean: Yes Undamaged: Yes Working:-		
2.30	Cupboard Side Panel	Clean: Yes Undamaged: Yes Working: Yes	New side panels	
2.31	Drawers	Clean: Yes Undamaged: Yes Working: Yes		
2.32	Washing Machine Taps	Clean: Yes Undamaged: Yes Working: Yes		
2.33	Washing Machine outlet	Clean:- Undamaged: Yes Working: Yes		
2.34	Floor/Carpets/ Tiles	Clean: Yes Undamaged: No	Hairline cracks over floor tiles	

2. KITCHEN (CONT.)					
2.35	Skirting (Tile / Wood)	Clean:	Yes		
		Undamaged:	Yes		
2.36	Door Stopper	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
2.37	Other	Clean:-Undamaged:-Working:-			
 26 Feb 2026 10:58 Ref #2  26 Feb 2026 10:58 Ref #2  26 Feb 2026 10:58 Ref #2  26 Feb 2026 10:58 Ref #2					
 26 Feb 2026 10:40 Ref #2.1  26 Feb 2026 10:40 Ref #2.1  26 Feb 2026 10:40 Ref #2.2					
 26 Feb 2026 10:40 Ref #2.2  26 Feb 2026 10:40 Ref #2.2  26 Feb 2026 10:40 Ref #2.2					

2. KITCHEN (CONT.)



26 Feb 2026 10:40

Ref #2.3




26 Feb 2026 10:40

Ref #2.3



26 Feb 2026 10:41

Ref #2.4



26 Feb 2026 10:41

Ref #2.5



26 Feb 2026 10:41

Ref #2.5



26 Feb 2026 10:41

Ref #2.7



26 Feb 2026 10:41

Ref #2.7



26 Feb 2026 10:41

Ref #2.7



26 Feb 2026 10:41

Ref #2.8



26 Feb 2026 10:41

Ref #2.9



26 Feb 2026 10:43

Ref #2.11



26 Feb 2026 10:44

Ref #2.12

2. KITCHEN (CONT.)




26 Feb 2026 10:44

Ref #2.12



26 Feb 2026 10:44

Ref #2.14



26 Feb 2026 10:45

Ref #2.15




26 Feb 2026 10:45

Ref #2.15




26 Feb 2026 10:45

Ref #2.15




26 Feb 2026 10:45

Ref #2.17




26 Feb 2026 10:45

Ref #2.17



26 Feb 2026 10:45

Ref #2.17



26 Feb 2026 10:45

Ref #2.17



26 Feb 2026 10:45

Ref #2.18



26 Feb 2026 10:45

Ref #2.18



26 Feb 2026 10:45

Ref #2.18

2. KITCHEN (CONT.)



Ref #2.19



Ref #2.19



Ref #2.19



Ref #2.20



Ref #2.20



Ref #2.20



Ref #2.21



Ref #2.21



Ref #2.23



Ref #2.23



Ref #2.23



Ref #2.24

2. KITCHEN (CONT.)



Ref #2.24



Ref #2.25



Ref #2.25



Ref #2.25



Ref #2.25



Ref #2.25




Ref #2.25



Ref #2.25



Ref #2.26



Ref #2.26



Ref #2.26



Ref #2.26

2. KITCHEN (CONT.)



26 Feb 2026 10:49

Ref #2.26



26 Feb 2026 10:49

Ref #2.27



26 Feb 2026 10:49

Ref #2.27



26 Feb 2026 10:50

Ref #2.27



26 Feb 2026 10:51

Ref #2.27



26 Feb 2026 10:52

Ref #2.27



26 Feb 2026 10:53

Ref #2.27



26 Feb 2026 10:53

Ref #2.30



26 Feb 2026 10:53

Ref #2.30



26 Feb 2026 10:53

Ref #2.30



26 Feb 2026 10:53


Ref #2.30









26 Feb 2026 10:53

Ref #2.31

2. KITCHEN (CONT.)



3. PASSAGE				
Ref	Name	Answers	Comments	Additional Comments
3.1	Ceiling & Cornice	Clean: Yes Undamaged: Yes		
3.2	Walls / Paint : Front	Clean: Yes Undamaged: Yes		
3.3	Walls / Paint : Left	Clean: Yes Undamaged: Yes		
3.4	Walls / Paint : Right	Clean: Yes Undamaged: No	Wall was not properly painted by the contractor. 2x white touch-up marks visible Needs Maintenance - Investigate	
3.5	Floor/Carpets/ Tiles	Clean: Yes Undamaged: No	Hairline cracks on tiles	

3. PASSAGE (CONT.)					
3.6	Skirting	Clean:	Yes		
		Undamaged:	Yes		
 Ref #3  Ref #3					
 Ref #3.1  Ref #3.4  Ref #3.4					
 Ref #3.4  Ref #3.4  Ref #3.4					
 Ref #3.4  Ref #3.5  Ref #3.5					

4. BEDROOM 1 / MAIN BEDROOM					
Ref	Name	Answers		Comments	Additional Comments
4.1	Doors	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
4.2	Door Frame	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
4.3	Striker Plate	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
4.4	Lock and Keys	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
4.5	Ceiling & Cornice	Clean:	Yes		
		Undamaged:	Yes		
4.6	Light Fittings / Cover	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
4.7	Light Switches	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
4.8	Bulbs	Clean:	Yes	No electricity	
		Undamaged:	Yes		
		Working:	Yes		
4.9	Curtains/Curtain Rail/Blinds	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		

4. BEDROOM 1 / MAIN BEDROOM (CONT.)

4.10	Window Panes	Clean: Yes Undamaged: Yes Working: Yes		
4.11	Windows Frames	Clean: Yes Undamaged: Yes Working: Yes		
4.12	Window Catches / Stay/ Latches	Clean: Yes Undamaged: Yes Working: Yes		
4.13	Walls / Paint : Front	Clean: Yes Undamaged: Yes		
4.14	Walls / Paint : Back	Clean: Yes Undamaged: Yes		
4.15	Walls / Paint : Left	Clean: Yes Undamaged: Yes		
4.16	Walls / Paint : Right	Clean: Yes Undamaged: Yes		
4.17	Cupboard Doors	Clean: Yes Undamaged: Yes Working: Yes		
4.18	Cupboard Shelves	Clean: Yes Undamaged: Yes Working: Yes		
4.19	Cupboard Rod	Clean: Yes Undamaged: Yes Working: Yes		

4. BEDROOM 1 / MAIN BEDROOM (CONT.)					
4.20	Cupboard Handles and Hindges	Clean: Undamaged: Working:	Yes Yes Yes		
4.21	Electrical Sockets and Switches	Clean: Undamaged: Working:	Yes Yes Yes		
4.22	Floor/Carpets/ Tiles	Clean: Undamaged:	Yes No	Hairline cracks on floor	
4.23	Skirting (Tile / Wood)	Clean: Undamaged:	Yes Yes		
4.24	Other	Clean:-Undamaged:-Working:-			



26 Feb 2026 10:30

Ref #4



26 Feb 2026 10:30

Ref #4



26 Feb 2026 10:30

Ref #4



26 Feb 2026 10:30

Ref #4



26 Feb 2026 10:30

Ref #4.1



26 Feb 2026 10:30









Ref #4.2











26 Feb 2026 10:30

Ref #4.2

4. BEDROOM 1 / MAIN BEDROOM (CONT.)




4. BEDROOM 1 / MAIN BEDROOM (CONT.)




5. BEDROOM 2					
Ref	Name	Answers		Comments	Additional Comments
5.1	Doors	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.2	Door Frame	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.3	Striker Plate	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.4	Lock and Keys	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.5	Ceiling & Cornice	Clean:	Yes		
		Undamaged:	Yes		
5.6	Light Fittings / Cover	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.7	Light Switches	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.8	Bulbs	Clean:	Yes	No electricity	
		Undamaged:	Yes		
		Working:	Yes		
5.9	Curtains/Curtain Rail/Blinds	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		

5. BEDROOM 2 (CONT.)					
5.10	Window Panes	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.11	Windows Frames	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.12	Window Catches / Stay/ Latches	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.13	Walls / Paint : Front	Clean:	Yes		
		Undamaged:	Yes		
5.14	Walls / Paint : Back	Clean:	Yes		
		Undamaged:	Yes		
5.15	Walls / Paint : Left	Clean:	Yes		
		Undamaged:	Yes		
5.16	Walls / Paint : Right	Clean:	Yes		
		Undamaged:	Yes		
5.17	Cupboard Doors	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.18	Cupboard Shelves	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
5.19	Cupboard Rod	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		

5. BEDROOM 2 (CONT.)					
5.20	Cupboard Handles and Hindges	Clean: Undamaged: Working:	Yes Yes Yes		
5.21	Electrical Sockets and Switches	Clean: Undamaged: Working:	Yes Yes Yes		
5.22	Floor/Carpets/ Tiles	Clean: Undamaged:	Yes No	Hairline cracks on floor tiles	
5.23	Skirting (Tile / Wood)	Clean: Undamaged:	Yes Yes		
5.24	Other	Clean:-Undamaged:-Working:-			



5. BEDROOM 2 (CONT.)



26 Feb 2026 10:23

Ref #5.2



26 Feb 2026 10:23

Ref #5.2



26 Feb 2026 10:23

Ref #5.4



26 Feb 2026 10:23

Ref #5.5



26 Feb 2026 10:23

Ref #5.6



26 Feb 2026 10:23

Ref #5.7




26 Feb 2026 10:24

Ref #5.9



26 Feb 2026 10:24

Ref #5.9



26 Feb 2026 10:24

Ref #5.10



26 Feb 2026 10:24

Ref #5.10



26 Feb 2026 10:34


Ref #5.10



26 Feb 2026 10:24

Ref #5.12


5. BEDROOM 2 (CONT.)




Ref #5.12



Ref #5.12




Ref #5.13




Ref #5.13




Ref #5.14




Ref #5.15



Ref #5.15




Ref #5.15




Ref #5.15



Ref #5.16




Ref #5.16



Ref #5.16

5. BEDROOM 2 (CONT.)



6. BATHROOM

Ref	Name	Answers	Comments	Additional Comments
6.1	Doors	Clean: Yes Undamaged: Yes Working: Yes		
6.2	Door Frame	Clean: Yes Undamaged: Yes Working: Yes		

6. BATHROOM (CONT.)					
6.3	Striker Plate	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.4	Door Stopper	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.5	Lock and Keys	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.6	Ceiling & Cornice	Clean:	Yes		
		Undamaged:	Yes		
6.7	Light Fittings / Covers	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.8	Light Switches	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.9	Bulbs	Clean:	Yes	No electricity	
		Undamaged:	Yes		
		Working:	Yes		
6.10	Curtains/Curtain Rail/Blinds	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.11	Window Panes	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.12	Windows Frames	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		

6. BATHROOM (CONT.)					
6.13	Window Catches / Stay/ Latches	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.14	Walls / Paint : Front	Clean:	Yes		
		Undamaged:	Yes		
6.15	Walls / Paint : Back	Clean:	Yes		
		Undamaged:	Yes		
6.16	Walls / Paint : Left	Clean:	Yes		
		Undamaged:	Yes		
6.17	Walls / Paint : Right	Clean:	Yes		
		Undamaged:	Yes		
6.18	Vanity Doors	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.19	Vanity Shelves	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.20	Vanity Handles and Hinges	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.21	Vanity Mirror	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.22	Towel Rails	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		

6. BATHROOM (CONT.)					
6.23	Hand Towel Rail	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.24	Bath	Clean:	Yes		
		Undamaged:	Yes		
6.25	Bath Hand Shower / Taps / Plug / Chain	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.26	Bath Soap Dish	Clean:	Yes		
		Undamaged:	Yes		
6.27	Basin	Clean:	Yes		
		Undamaged:	Yes		
6.28	Basin / Tap / Plug / Chain	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.29	Toilet Pan / Seat / Cistern / Outlet Pipe	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.30	Toilet Roll Holder	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
6.31	Shower Doors / Door Rollers	Clean:	Yes		
		Undamaged:	Yes		
6.32	Shower Walls	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		

6. BATHROOM (CONT.)


6.33	Shower Floor	Clean: Yes Undamaged: Yes Working: Yes		
6.34	Shower Drain Grid	Clean: Yes Undamaged: Yes Working: Yes		
6.35	Shower Taps/ Rose	Clean: Yes Undamaged: Yes Working: Yes		
6.36	Shower Soap Dish	Clean: Yes Undamaged: Yes		
6.37	Floor/Tiles	Clean: Yes Undamaged: Yes	Hairline cracks on floor tiles	
6.38	Skirting	Clean: Yes Undamaged: Yes		
6.39	Other	Clean:-Undamaged:-Working:-		



Ref #6



Ref #6

6. BATHROOM (CONT.)		
 26 Feb 2026 10:11 Ref #6.1	 26 Feb 2026 10:11 Ref #6.1	 26 Feb 2026 10:12 Ref #6.2
 26 Feb 2026 10:12 Ref #6.2	 26 Feb 2026 10:12 Ref #6.2	 26 Feb 2026 10:12 Ref #6.3
 26 Feb 2026 10:12 Ref #6.4	 26 Feb 2026 10:12 Ref #6.5	 26 Feb 2026 10:12 Ref #6.6
 26 Feb 2026 10:12 Ref #6.6	 26 Feb 2026 10:12 Ref #6.7	 26 Feb 2026 10:13 Ref #6.8

6. BATHROOM (CONT.)




26 Feb 2026 10:13

Ref #6.10



26 Feb 2026 10:13

Ref #6.12




26 Feb 2026 10:14

Ref #6.13




26 Feb 2026 10:14

Ref #6.13




26 Feb 2026 10:14

Ref #6.14



26 Feb 2026 10:14

Ref #6.14




26 Feb 2026 10:14

Ref #6.15




26 Feb 2026 10:14

Ref #6.15




26 Feb 2026 10:14

Ref #6.16




26 Feb 2026 10:15

Ref #6.16



26 Feb 2026 10:15










Ref #6.17



26 Feb 2026 10:15

Ref #6.17

6. BATHROOM (CONT.)



6. BATHROOM (CONT.)



26 Feb 2026 10:16
Ref #6.24



26 Feb 2026 10:17
Ref #6.25



26 Feb 2026 10:17
Ref #6.25



26 Feb 2026 10:17
Ref #6.25



26 Feb 2026 10:17
Ref #6.26



26 Feb 2026 10:17
Ref #6.27



26 Feb 2026 10:17
Ref #6.27



26 Feb 2026 10:17
Ref #6.28



26 Feb 2026 10:17
Ref #6.28



26 Feb 2026 10:18
Ref #6.29









26 Feb 2026 10:18
Ref #6.29




26 Feb 2026 10:18
Ref #6.29

6. BATHROOM (CONT.)







6. BATHROOM (CONT.)





7. PATIO					
Ref	Name	Answers		Comments	Additional Comments
7.1	Ceiling & Cornice	Clean:	Yes	No electricity	
		Undamaged:	Yes		
7.2	Light Fittings / Cover	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
7.3	Light Switches / Cover	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
7.4	Bulbs	Clean:	Yes		
		Undamaged:	Yes		
		Working:	Yes		
7.5	Walls / Paint : Front	Clean:	Yes		
		Undamaged:	Yes		

7. PATIO (CONT.)				
7.6	Walls / Paint : Left	Clean: Undamaged:	Yes Yes	Chip mark on pillar
7.7	Walls / Paint : Right	Clean: Undamaged:	Yes Yes	
7.8	Floor/Tiles	Clean: Undamaged:	Yes No	Tile cracked
7.9	Other	Clean:-Undamaged:-Working:-		



7. PATIO (CONT.)



8. KEYS

Ref	Name	Description	Additional Comments
8.1	List House Keys	Front Security Gate -2x keys Night Latch - 2x new keys Back Door - CI DL x1 & CISA key Back Door Security Gate - TRI 5I x2 keys Bathroom - M26H x1 key Main Bedroom - Bedroom 2 - M30H x1 key	
8.2	Remotes/Discs	1X Remote Remote does not open entrance gate 1X Access Tag Needs Maintenance - Landlord	

8. KEYS (CONT.)



25 Feb 2026 19:07

Ref #8



25 Feb 2026 19:11

Ref #8



25 Feb 2026 19:12

Ref #8



25 Feb 2026 19:14

Ref #8



26 Feb 2026 10:21

Ref #8



26 Feb 2026 10:27

Ref #8



25 Feb 2026 19:08

Ref #8.2



25 Feb 2026 19:08

Ref #8.2

Declaration

I/We the undersigned, affirm that if I/we do not comment on the Inspection in writing within seven days of receipt of this Inspection then I/we accept the Inspection as being an accurate record of the contents and condition of the property.

Signed by the Tenant



BLESSING TSHUMA

26 / 02 / 2026 11:31

Signed by the

Signatures

Print Name

Date / /

Appendix

Comment Summary

Ref	Comments
-----	----------

UNANSWERED

Ref	Room Name
2	Living Room/ Lounge/ Open Plan
5	Kitchen
7	Passage
8	Bedroom 1 / Main Bedroom
9	Bedroom 2
14	Bathroom
17	Patio
25	Keys