DNV

INSPECTION REPORT
OF HAND PALLET TRUCK

Report No:
A1853836-01
Date of Inspection:
4 January 2026

Particulars of Owner

Name of Owner:	**M/s. SULZER ROTATING EQUIPMENT SERVICES**
Address of Owner:	**DOHA, STATE OF QATAR**
Place of Inspection:	**DUTEST QATAR**
DNV NPS W/O Number:	**WO# 17462209088**
	A1853836

Scheme of Examination

Type of Inspection: **In-Service Thorough Examination**

As requested by the equipment owner, the undersigned surveyor of this organization, attended their facility to carry out SWL test & thorough examination of the below item and report the findings as here under:

Particulars of Equipment

Equipment Name and Description:	**Manually Operated Hydraulic Hand Pallet Truck**
Manufacturer Name:	**HEBER**
Serial Number/ID No:	**63180001**
Model No.:	**SBT-IIIA**
Max fork height:	**190 mm**
Min fork height:	**90 mm**
Fork length:	**1200 mm**
Overall fork width:	**680 mm**
Stroke Height:	**100 mm**
SWL:	**5.0 t**
SWL test applied:	**5.0 t**

Additional Equipment Parameters (If Any)

Measuring Tape ID No.: VC4-TAG-401, Due Date: 20.05.2026	*Measuring Tape ID No.: VC4-TAG-401, Due Date: 20.05.2026*

Result of Inspection

The above-mentioned equipment was SWL test & thoroughly inspected for safe operating conditions. The item was found in satisfactory condition during the time of inspection. The above item was inspected and a report issued as per client requirement.

Previous Examination Details: **8 May 2025,** (TRG12C2025-994)

Date of Next Examination: **4 July 2026**

Authorized Name: ***ROBIN JOHNY***

Surveyor's Name: ***AHMED GABER***

Authorized Signature:

Surveyor's Signature:

© DNV 2014. DNV and the Horizon Graphic are trademarks of DNV AS.